

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**

**Asset: I.S. 211 - BROOKLYN, 1001 EAST 100 STREET, New York, 11236**

Inspection Id	Inspection Type	Time In	Last Edited
SA : K211	Architectural - Senior	2023-11-30 7:30 AM	2024-06-16 9:49 AM
AA : K211	Architectural - Associate	2023-11-30 8:04 AM	2023-12-21 5:35 PM

**Asset Data**

Question	Answer
Was the building fully accessible for inspection	No
Inspection Access Comment	Showers - Basement - Boys, Girls, Science Lab - Room 209, Science Prep - Room 203 (storage)
Building Square Footage	140,000
Comments on the Area (for Athletic Field, Playing Surfaces, Leased Spaces)	None
Comments on the Stories (Floors) plus Basements	3+B
Comments on the Number of Classrooms	63
Comments on the Year Built	1958
Student Population	635
Staff Population	115
Weather	Fair
Principal(s) Information	
Principal Name	Carolyn James
Organization	I.S. 211 - Brooklyn
Did you meet with this Principal?	Yes
Did this Principal provide feedback?	Yes
Summary of Principal's Feedback	The Principal's comments are as follows: 1. There is a loose step in Stairwell H. 2. There are interior doors that are deteriorated. 3. Several windows have inoperable balances presenting a hazard. 4. The gymnasium flooring has water damage.
Principal Name	Michael Loughren
Organization	Leadership Prep Canarsie Charter School - Brooklyn
Did you meet with this Principal?	No
Did this Principal provide feedback?	No
Custodian	Vinod Harripaul
Fireman	Jonathan Jewnath
Facade Photo	



Corner of East 100th Street and Avenue J - East View

NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection


K211

Main Entrance Photo



Facade A - East 100th Street

Roof Photo



Roof 1 - Northwest View

Have any Systems/Major Building Components been upgraded?

Yes

Systems: Exterior Stairs and Flank Walls - repairs, Ash Hoist Vault Doors - replacement

Year: 2022

Systems: Areaway Stairs repairs; Exterior Doors repairs; Foundation Walls repairs.

Year: 2021

Systems: Exterior Doors repairs.

Year: 2020

Systems: Exterior Doors and Frames repairs; Dunnage replacement at Roof 1; Skylight removed.

Year: 2017

Systems: Sidewalk Elevator removed.

Year: 2014

Systems: Roofing replacement; Parapets and Coping replacement; Roof Drains and Roof Barriers replacement; Bulkhead and Chimney repairs.

Year: 2012

Systems: Areaway, Foundation Walls repairs.

Year: 2011

Systems: Chimney repairs.



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

	Year:	2010
	Systems:	Partial Exterior Walls repairs.
	Year:	2007
	Systems:	Windows and Window Guards replacement.
	Year:	1996
	Systems:	Exterior Ramp replacement.
	Year:	1984
Have there been any Building Additions?	No	
Tandem Schools?	No	
Leased Space?	No	

Priority Condition

Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No	Tripping Hazard	Severely damaged step is a potential safety hazard.	INTERIOR   STAIRS/RAMP S: INTERIOR   Stairs and Landings	Stair H/2	Jonathan Jewnath	Fireman	
Yes	Tripping Hazard	A concrete stair is cracked and broken presenting a hazard.	EXTERIOR   STAIRS/RAMP S: EXTERIOR   STAIRS/RAMP S	Southeast corner of facade facing East 101st Street	Jonathan Jewnath	Fireman	

Structural Engineer Required

Structural Condition Type	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	PhotoImage
No condition recorded						

Programmatic Accessibility

Programmatic Accessibility Status Question	Response
Is the primary or secondary entrance on an accessible route?	Yes
Is the building a multi-story building?	Yes
Are all floors of the building accessible through compliant means?	Yes
Accessible classrooms exists on each floor?	Yes
Boys and Girls or Unisex accessible toilets exist on at least every other floor?	Yes
If the following spaces exist, are they ALL accessible? Art Room, Auditorium, Cafeteria, Computer, Gymnasiums, Library, Multipurpose Room, Science Labs	Yes

Physical Breakdown Structure	Exists	Required	Complies	Deficiency	Assistive Fire Listening System	Fire Alarm Strobe
------------------------------	--------	----------	----------	------------	---------------------------------	-------------------

**PROGRAMMATIC ACCESSIBILITY**

**Exterior Routes**

Exterior Entrances & Exits			Yes	
Exterior H/C Lifts	No	No		
Exterior Ramps and Railings	Yes		Yes	

**Interior Routes**

Corridor and Lobby H/C Lifts	No	No		
Interior Corridor Doors and Hardware	Yes		Yes	


**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Physical Breakdown Structure		Exists	Required	Complies	Deficiency	Assistive Listening System	Fire Alarm Strobe
<b>Interior Routes</b>							
Interior Corridors and Lobbies				Yes			
Interior Elevators		Yes		Yes			
Interior Lobby Doors and Hardware				Yes			
Interior Ramps		No					
<b>Rooms &amp; Spaces</b>							
Art Rooms	Room 213	Yes		Yes			
Auditorium	1st Floor	Yes		Yes		FM System	Yes
Cafeteria	Basement - Staff	Yes		Yes		No	Yes
	Basement - Students	Yes		Yes		FM System	Yes
Classrooms	Basement, 1st-3rd Floors	Yes		Yes			
Computer Rooms	Room 204	Yes		Yes			
Gymnasium	1st Floor	Yes		Yes		FM System	Yes
Library	2nd Floor	Yes		Yes			
Main Office	Room 123 (I.S. 211), Room 327 (Leadership Prep Canarsie Charter School)	Yes		Yes			
Multi-purpose Room		No					
Nurse's Room	Room 124	Yes		Yes			
Pool		No					
Science Lab	Room 209	Yes		Yes			
Toilet Rooms (Boys)	Basement, 1st-3rd Floors	Yes		Yes			
Toilet Rooms (Girls)	Basement, 1st-3rd Floors	Yes		Yes			
Toilet Rooms (Staff)	1st, 3rd Floors	Yes		Yes			

Building Template



Inspection




Question	Response
----------	----------



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>Architectural</b>	
<b>EXTERIOR</b>	Inspected
<b>AREAWAY</b>	Inspected
Instance on AW1-AW5	Inspected
Instance Condition	3 - Fair
Instance Quantity	5
Instance Quantity Uom	EACH
Deficiency	AREAWAY WALLS: CRACKS AND SPALLING
Roof Plan reference	
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	AW1 No violations recorded.
Deficiency	AREAWAY SLAB: CRACKS AND SPALLING
Roof Plan reference	
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question

Response

**EXTERIOR**

**AREAWAY**

Deficiency Photo1



AW1


Violations

No violations recorded.

Deficiency

AREAWAY SLAB: CRACKS AND SPALLING

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



AW1


Violations

No violations recorded.

Deficiency

AREAWAY WALLS: CRACKS AND SPALLING

Roof Plan reference



Deficiency Quantity

60

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

# NYC Department of Education

## Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>AREAWAY</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	AW3 No violations recorded.
<b>AWNINGS AND CANOPIES</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CHIMNEY</b>	Inspected
Material Type(s)	Masonry
Condition	3 - Fair
Deficiency	BRICK: DETERIORATED CAP
Roof Plan reference	
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Chimney No violations recorded.
Deficiency	BRICK: MINOR CRACKS AND SPALLING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**


**Question**

**Response**

**EXTERIOR**

**CHIMNEY**

Roof Plan reference



Deficiency Quantity

40

Quantity Uom

S.F.

Potential Action

RESTITCH


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Violations


Chimney

No violations recorded.

Deficiency

BRICK: DETERIORATED JOINTS

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Violations




Chimney

No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>COPING</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CORNICE</b>	Does not Exist
<b>DOORS</b>	Inspected
<b>DOORS AND FRAMES</b>	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION
Roof Plan reference	
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade D No violations recorded.
Deficiency	METAL: DETERIORATED DOOR AND FRAME - MAJOR DETERIORATION
Roof Plan reference	
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2


## Architectural Inspection

K211

## Facade D

No violations recorded.

METAL: DETERIORATED DOOR AND FRAME - MINOR  
DETERIORATION




1

EACH

## MAINTENANCE

### PRIORITY 3

## LEVEL 2



### Facade C

No violations recorded.

## DOOR HARDWARE

Inspected

### Condition

3 - Fair

### Deficiency

No deficiencies recorded

## LINTELS

Inspected

### Condition

3 - Fair

Deficiency

STEEL: MAJOR RUSTING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


Question	Response
----------	----------

**EXTERIOR**

**DOORS**

**LINTELS**

Roof Plan reference



Deficiency Quantity

35

Quantity Uom

L.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C

Violations

No violations recorded.

**TRANSOM/SIDE LIGHT**

Inspected


Condition

3 - Fair

Deficiency

METAL: BROKEN GLASS

Roof Plan reference



Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action




LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>DOORS</b>	Inspected
<b>TRANSOM/SIDE LIGHT</b>	
Deficiency Photo1	
Violations	<p>Facade D</p> <p>No violations recorded.</p>
<b>EXTERIOR WALLS</b>	Inspected
Material Type(s)	Masonry
Replacement Quantity	33,000
Replacement Uom	S.F.
Instance on All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	33,000
Instance Quantity Uom	S.F.
Deficiency	BRICK: DETERIORATED JOINTS
Roof Plan reference	
Elevation	
Deficiency Quantity	75
Quantity Uom	S.F.
Potential Action	REPOINT
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Deficiency Photo1

Inspected



Facade F


No violations recorded.

Violations


Deficiency

Roof Plan reference

**BRICK: DETERIORATED JOINTS**



Elevation



Deficiency Quantity

30

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade F

No violations recorded.

Violations

Deficiency

**BRICK: DETERIORATED CONTROL/EXPANSION JOINTS**

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


Question

Response


**EXTERIOR**

**EXTERIOR WALLS**

Roof Plan reference



Elevation



Deficiency Quantity

40

Quantity Uom

L.F.

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade F


No violations recorded.

Violations

Deficiency

BRICK: DETERIORATED MASONRY SILLS - MAJOR

Roof Plan reference



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Elevation



Deficiency Quantity

40

Quantity Uom

L.F.

Potential Action

REMOVE AND REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C


No violations recorded.

Violations


Deficiency

BRICK: MAJOR / THRU CRACKS

Roof Plan reference



Elevation



Deficiency Quantity

20

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question

Response

**EXTERIOR**

**EXTERIOR WALLS**

Deficiency Photo1



Facade C


No violations recorded.

Violations


Deficiency

BRICK: DETERIORATED MASONRY SILLS - MINOR

Roof Plan reference



Elevation



Deficiency Quantity

45

Quantity Uom

L.F.

Potential Action

REPAIR


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C

No violations recorded.

Violations

Deficiency

BRICK: MINOR CRACKS AND SPALLING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


Question

Response

**EXTERIOR**

**EXTERIOR WALLS**

Roof Plan reference



Elevation



Deficiency Quantity

110

Quantity Uom

S.F.

Potential Action

RESTITCH

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Violations


Facade C

No violations recorded.

Deficiency

BRICK: CRACKS/DISPLACED/SPALLED BRICK AT BUILDING CORNERS

Roof Plan reference





**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Elevation



Deficiency Quantity

60

Quantity Uom

S.F.

Potential Action

REMOVE AND REBUILD

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade C


Violations

No violations recorded.

Deficiency

BRICK: MASONRY SILLS - DETERIORATED JOINTS

Roof Plan reference



Elevation



Deficiency Quantity

100

Quantity Uom

L.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

**Question**

**Response**

**EXTERIOR**

**EXTERIOR WALLS**

Deficiency Photo1



Facade B


No violations recorded.

Violations


Deficiency

Roof Plan reference

STONE: DETERIORATED JOINTS



Elevation



Deficiency Quantity

20

Quantity Uom

L.F.

Potential Action

REPOINT

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade B

No violations recorded.

Violations

**EXTERIOR SOFFITS**

Inspected

Condition

2 - Between Good and Fair

Deficiency

No deficiencies recorded

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>LOADING DOCK</b>	Does not Exist
<b>LOUVER</b>	Inspected
Condition	3 - Fair
Deficiency	BROKEN/ DENTED BLADES
Roof Plan reference	
Elevation	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade A</p> <p>No violations recorded.</p>
<b>PARAPETS</b>	Inspected
Material Type(s)	Masonry
Replacement Quantity	2,000
Replacement Uom	C.F.
Instance on Roofs 1, 2	Inspected
Instance Condition	3 - Fair
Instance Quantity	2,000
Instance Quantity Uom	C.F.
Deficiency	BRICK: DETERIORATED JOINTS

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


**Question**

**Response**

**EXTERIOR**

**PARAPETS**

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPOINT


Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Violations


Roof 2

No violations recorded.

Deficiency

BRICK: EFFLORESCENCE

Roof Plan reference



Deficiency Quantity

100

Quantity Uom

S.F.

Potential Action

MAINTENANCE

Urgency of Action

PRIORITY 1

Purpose of Action

LEVEL 1

Deficiency Photo1



Violations


Roof 2

No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




K211

Question	Response
<b>EXTERIOR</b>	
<b>PLAZA DECK</b>	Does not Exist
<b>ROOF</b>	Inspected
<b>Roofing</b>	Inspected
Replacement Quantity	45,000
Replacement Uom	S.F.
<b>ROOF HATCH/SMOKE HATCH</b>	Does not Exist
<b>LEADERS, GUTTERS, DOWNSPOUTS, SCUPPERS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>ROOF BARRIER/FENCE</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>ROOF CAGE</b>	Does not Exist
<b>ROOFING</b>	Inspected
Instance on Modified Bitumen: All Roofs	Inspected
Instance Condition	3 - Fair
Instance Photo	
	Roof 1
Instance Quantity	45,000
Instance Quantity Uom	S.F.
Does the roof have major mechanical equipment sitting on Dunnage Steel less than 18" above the Roofing?	No
Does this roof instance have a Sustainable Roof System?	Yes
Sustainable Roof Type	White Roof
Sustainable Roof Location (Roof Number)	All Roofs
Do solar panels exist on these roofs?	No
Is/Are the roof(s) suitable for Solar Panel installation?	Yes
Installation Year	2012
Source of Installation	Custodial Staff
Deficiency	MODIFIED BITUMEN: ROOFING: DELAMINATION
Roof Plan reference	
Deficiency Quantity	310
Quantity Uom	S.F.
Potential Action	REPLACE ROOFING WITHOUT MAJOR EQUIPMENT REMOVAL
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Roofing</b>	
<b>ROOFING</b>	
Deficiency Photo1	
Violations	Roof 1 No violations recorded.
<b>ROOFING DRAINS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Specialties</b>	Inspected
<b>BULKHEAD/PENTHOUSE</b>	Inspected
Condition	3 - Fair
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: CRACKS/SPALLING - MINOR
Roof Plan reference	
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	BH2 No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE WALLS/EXTERIOR: DETERIORATED JOINTS

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**


Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	

**BULKHEAD/PENTHOUSE**

Roof Plan reference



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo1


180  
S.F.  
REPOINT  
PRIORITY 3  
LEVEL 2



BH3  
No violations recorded.

Violations

Deficiency	<b>BULKHEAD/PENTHOUSE WALLS/INTERIOR: GLAZED BLOCK CRACKS/SPALLING</b>
Roof Plan reference	



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action

40  
S.F.  
REPLACE  
PRIORITY 4  
LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
----------	----------

**EXTERIOR**

**ROOF**

**Specialties**

**BULKHEAD/PENTHOUSE**

Deficiency Photo1



BH3


Violations

No violations recorded.

Deficiency

**BULKHEAD/PENTHOUSE WALLS/INTERIOR: GLAZED BLOCK CRACKS/SPALLING**

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



BH3


Violations

No violations recorded.

Deficiency

**BULKHEAD/PENTHOUSE CEILING: PLASTER DAMAGED/DETERIORATED**

Roof Plan reference








**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	
<b>BULKHEAD/PENTHOUSE</b>	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	BH3 No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE ROOF: MINOR LEAKAGE
Roof Plan reference	
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	BH3 No violations recorded.
Deficiency	BULKHEAD/PENTHOUSE WALLS/INTERIOR: PLASTER CRACKS/SPALLING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**


Architectural Inspection

**K211**

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	

**BULKHEAD/PENTHOUSE**

Roof Plan reference



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action  
Deficiency Photo1

15  
S.F.  
REPLACE  
PRIORITY 4  
LEVEL 2




BH3  
No violations recorded.

Violations

Deficiency	<b>BULKHEAD/PENTHOUSE WALLS/EXTERIOR: WATER INFILTRATION</b>
------------	--

Roof Plan reference



Deficiency Quantity  
Quantity Uom  
Potential Action  
Urgency of Action  
Purpose of Action

50  
S.F.  
REPAIR  
PRIORITY 5  
LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




**K211**

Question	Response
<b>EXTERIOR</b>	
<b>ROOF</b>	
<b>Specialties</b>	
<b>BULKHEAD/PENTHOUSE</b>	Inspected
Deficiency Photo1	
	BH3
Violations	No violations recorded.
<b>CUPOLA/ SPIRES/ TOWERS</b>	Does not Exist
<b>DORMER</b>	Does not Exist
<b>DUNNAGE STEEL</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>SKYLIGHT/ROOF VENT</b>	Inspected
Material Type(s)	Glass
Condition	3 - Fair
Deficiency	DAMAGED GUARDS
Roof Plan reference	
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	SK
Violations	No violations recorded.
<b>ROOF/GRAVITY TANK</b>	Does not Exist
<b>STAIRS/RAMPS: EXTERIOR</b>	Inspected

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>STAIRS/RAMPS: EXTERIOR</b>	
<b>BUILDING CHEEK/FLANK WALLS</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	STONE: DETERIORATED JOINTS
Roof Plan reference	
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPOINT
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade A</p> <p>No violations recorded.</p>
Deficiency	STONE: CRACKS/SPALLING - MAJOR
Roof Plan reference	
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

**Question**

**Response**

**EXTERIOR**

**STAIRS/RAMPS: EXTERIOR**

**BUILDING CHEEK/FLANK WALLS**

Deficiency Photo1



Facade E


No violations recorded.

Violations

Deficiency

Roof Plan reference

**STONE: CRACKS/SPALLING - MINOR**



K211



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPAIR

Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade E

No violations recorded.

Violations

**RAILINGS**

Inspected


Condition

5 - Poor

Deficiency

DAMAGED

Roof Plan reference



K211






Deficiency Quantity

10

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**

Question	Response
<b>EXTERIOR</b>	
<b>STAIRS/RAMPS: EXTERIOR</b>	
<b>RAILINGS</b>	
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade B</p> <p>No violations recorded.</p>
Deficiency	RUST - MAJOR
Roof Plan reference	
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade B</p> <p>No violations recorded.</p>
<b>STAIRS/RAMPS</b>	Inspected
Condition	5 - Poor
Deficiency	CONCRETE: CRACKS/SPALLING - MAJOR

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**


Question	Response
----------	----------

**EXTERIOR**

**STAIRS/RAMPS: EXTERIOR**

**STAIRS/RAMPS**

Roof Plan reference



Deficiency Quantity

25

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 5

Purpose of Action

LEVEL 6

Deficiency Photo1



Facade C


Violations

No violations recorded.

Deficiency

STONE: CRACKS/SPALLING - MINOR

Roof Plan reference



Deficiency Quantity

10

Quantity Uom

S.F.

Potential Action

REPAIR


Urgency of Action

PRIORITY 3

Purpose of Action

LEVEL 2

Deficiency Photo1






Facade C



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>STAIRS/RAMPS: EXTERIOR</b>	
<b>STAIRS/RAMPS</b>	
Violations	No violations recorded.
Deficiency	CONCRETE: CRACKS/SPALLING - MINOR
Roof Plan reference	
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Facade B
Deficiency	STONE: DETERIORATED JOINTS
Roof Plan reference	
Deficiency Quantity	25
Quantity Uom	L.F.
Potential Action	REPOINT
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**

**Question**

**Response**

**EXTERIOR**

**STAIRS/RAMPS: EXTERIOR**

**STAIRS/RAMPS**

Deficiency Photo1



Facade A


Violations

No violations recorded.

Deficiency

STONE: CRACKS/SPALLING - MAJOR

Roof Plan reference



Deficiency Quantity

15

Quantity Uom

S.F.

Potential Action

REPLACE

Urgency of Action

PRIORITY 4

Purpose of Action

LEVEL 2

Deficiency Photo1



Facade A


Violations

No violations recorded.

Deficiency

STONE: DETERIORATED JOINTS

Roof Plan reference



Deficiency Quantity

35

Quantity Uom

L.F.




Potential Action

REPOINT

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




**K211**

Question	Response
<b>EXTERIOR</b>	
<b>STAIRS/RAMPS: EXTERIOR</b>	
<b>STAIRS/RAMPS</b>	
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	<p>Facade A</p> <p>No violations recorded.</p>
<b>WINDOWS</b>	Inspected
Replacement Quantity	12,000
Replacement Uom	S.F.
<b>EXTERIOR GUARDS</b>	Inspected
Condition	3 - Fair
Deficiency	DETERIORATED/TORN-OUT/MISSING
Roof Plan reference	
Elevation	
Deficiency Quantity	120
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>EXTERIOR</b>	
<b>WINDOWS</b>	
<b>EXTERIOR GUARDS</b>	
Deficiency Photo1	
Violations	<p>Facade E</p> <p>No violations recorded.</p>
<b>LINTELS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>WINDOWS</b>	Inspected
Material Type(s)	Aluminum
Instance on Aluminum - Double Hung: All Facades	Inspected
Instance Condition	3 - Fair
Instance Quantity	12,000
Instance Quantity Uom	S.F.
Are these windows insulated	No
Installation Year	1996
Source of Installation	Custodial Staff
Deficiency	ALUMINUM - DOUBLE HUNG: INOPERABLE BALANCE
Roof Plan reference	
Elevation	
Deficiency Quantity	120
Quantity Uom	EACH
Potential Action	REPLACE BALANCES
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>EXTERIOR</b>	
<b>WINDOWS</b>	
<b>WINDOWS</b>	
Deficiency Photo1	
Violations	Facade A No violations recorded.
<b>INTERIOR</b>	Inspected
<b>POOLS</b>	Does not Exist
<b>STRUCTURAL</b>	Inspected
<b>COLUMNS/BEAMS/BEARING WALLS</b>	Inspected
Condition	3 - Fair
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED MASONRY FIREPROOFING
Deficiency Location/Instance	Basement
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Gas Meter Room No violations recorded.
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED CONCRETE FIREPROOFING
Deficiency Location/Instance	Basement
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>COLUMNS/BEAMS/BEARING WALLS</b>	
Deficiency Photo1	
Violations	Boiler Room No violations recorded.
Deficiency	STEEL COLUMNS/BEAMS: DETERIORATED CONCRETE FIREPROOFING
Deficiency Location/Instance	Basement
Deficiency Quantity	35
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Boiler Room No violations recorded.
<b>FLOOR STRUCTURE</b>	Inspected
Condition	3 - Fair
Deficiency	CONCRETE SLAB ON GRADE: THRU CRACKS
Deficiency Location/Instance	Basement
Deficiency Quantity	55
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211




Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>FLOOR STRUCTURE</b>	
Deficiency Photo1	
Violations	Boiler Room (Gas Meter Room, Electrical Panel Room similar) No violations recorded.
Deficiency	CONCRETE: CRACKS/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Basement, 2nd Floor
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Room B23 (Rooms B3, 240 similar) No violations recorded.
<b>FOUNDATION WALLS</b>	
Material Type(s)	Inspected Concrete, Masonry
Condition	4 - Between Fair and Poor
Deficiency	CONCRETE: CRACKED/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Basement
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>FOUNDATION WALLS</b>	
Deficiency Photo1	
Violations	Room B29 No violations recorded.
Deficiency	BRICK: CRACKED/SPALLED
Deficiency Location/Instance	Basement
Deficiency Quantity	35
Quantity Uom	S.F.
Potential Action	RESTITCH
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Cafeteria Fan Room No violations recorded.
Deficiency	CONCRETE: WATER INFILTRATION IN NON- INSTRUCTIONAL SPACE
Deficiency Location/Instance	Basement
Deficiency Quantity	300
Quantity Uom	S.F.
Potential Action	INSTALL WATERPROOFING
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 5
Deficiency Photo1	
	Room B29A (Cafeteria Fan Room similar)



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K211

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>FOUNDATION WALLS</b>	Inspected
Violations	No violations recorded.
<b>ROOF STRUCTURE</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>VAULTS-BUNKERS</b>	Inspected
<b>Foundation Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	CRACKS, SPALLING
Deficiency Location/Instance	Vault
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Vault No violations recorded.
<b>Slab Structure</b>	Inspected
Condition	3 - Fair
Deficiency	CONCRETE: CRACKS/SPALLED/REINFORCEMENT EXPOSED
Deficiency Location/Instance	Vault
Deficiency Quantity	25
Quantity Uom	S.F.
Potential Action	REPAIR
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Vault No violations recorded.
Deficiency	STEEL COLUMNS/BEAMS: MAJOR RUSTING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K211

Question	Response
<b>INTERIOR</b>	
<b>STRUCTURAL</b>	
<b>VAULTS-BUNKERS</b>	
<b>Slab Structure</b>	
Deficiency Location/Instance	Vault
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 5
Deficiency Photo1	
Violations	Vault No violations recorded.
<b>Vault/Ash Hoist Doors and Framing</b>	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>AUDITORIUM</b>	Inspected
Instance on 1st Floor (506 seats)	Inspected
<b>Ceiling</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
<b>Door(s)</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Door(s)</b>	
Deficiency	No deficiencies recorded
<b>Fixed H/C Lift</b>	
Instance on 1st Floor (506 seats)	Does not Exist
<b>Fixed Seating</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Right side Exit Vestibule, left side exit Vestibule
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Right side exit Vestibule No violations recorded.
<b>Sliding-folding Partition</b>	
Instance on 1st Floor (506 seats)	Does not Exist
<b>Stage</b>	
Instance on 1st Floor (506 seats)	Inspected
<b>Stage</b>	Inspected
Instance on 1st Floor (506 seats)	Inspected
Condition	3 - Fair
Deficiency	DAMAGED FLOOR
Deficiency Location/Instance	Center
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Stage</b>	
<b>Stage</b>	
Deficiency Photo1	
Center	Center
Violations	No violations recorded.
Deficiency	DAMAGED STEPS
Deficiency Location/Instance	Right side, left side
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Right side	Right side
Violations	No violations recorded.
<b>Stage Curtain Rigging</b>	Inspected
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stage Curtains</b>	Inspected
Instance on 1st Floor (506 seats)	Inspected
Condition	4 - Between Fair and Poor
Deficiency	WORN/DETERIORATED
Deficiency Location/Instance	Left side
Deficiency Quantity	300
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Stage</b>	
<b>Stage Curtains</b>	
Deficiency Photo1	
	Left side
Violations	No violations recorded.
<b>Walls</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	MASONRY: CRACKS/SPALLING
Deficiency Location/Instance	Stage
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Stage
Violations	No violations recorded.
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Right side exit Vestibule
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>AUDITORIUM</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Right side exit Vestibule No violations recorded.
<b>Window Curtains/Shades/Blinds</b>	
Instance on 1st Floor (506 seats)	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>CAFETERIA</b>	
Instance on Basement - Staff	Inspected
Instance on Basement - Student	Inspected
<b>Ceiling</b>	
Instance on Basement - Student	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Near elevator/Basement
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near elevator/Basement No violations recorded.
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>CAFETERIA</b>	
<b>Ceiling</b>	
Deficiency Photo1	
Violations	Near Windows No violations recorded.
<b>Door(s)</b>	
Instance on Basement - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Student	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Equipment</b>	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Student	Does not Exist
<b>Floor Finish</b>	
Instance on Basement - Staff	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Basement - Student	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Sliding-folding Partition</b>	
Instance on Basement - Student	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>Stage</b>	
Instance on Basement - Staff	Does not Exist
Instance on Basement - Student	Does not Exist
<b>Walls</b>	
Instance on Basement - Student	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211




Question	Response
<b>INTERIOR</b>	
<b>CAFETERIA</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Near Windows No violations recorded.
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Near Windows, mechanical room, kitchen
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Windows No violations recorded.
<b>Window Curtains/Shades/Blinds</b>	
Instance on Basement - Student	Does not Exist
Instance on Basement - Staff	Does not Exist
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
Inspected	Inspected
<b>Ceiling</b>	
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Room 332, Corridor near Room 232
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



**K211**

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Ceiling</b>	
Deficiency Photo1	
Violations	Room 332 No violations recorded.
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING - ACTIVE LEAK
Deficiency Location/Instance	Room B38
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room B38 No violations recorded.
Deficiency	ACOUSTIC TILES ON PLASTER: DAMAGED/MISSING
Deficiency Location/Instance	Corridor near Rooms 236,234,230, Stair B/5,2, and others
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Corridor near Stair B/2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Ceiling</b>	Inspected
Violations	No violations recorded.
<b>Door(s)</b>	Inspected
Condition	5 - Poor
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 312,307
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 307
Violations	No violations recorded.
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room 329A,328,323,310,223, and others
Deficiency Quantity	20
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 310
Violations	No violations recorded.
<b>Floor Finish</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	TERRAZZO: CRACKS
Deficiency Location/Instance	Exits 7,5,4,3,2, and others
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Floor Finish</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Exit 7 No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	Corridor near Room 324,312,310,309, Elevator/3, and others
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Elevator/3 No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	STONE: CRACKS/SPALLING
Deficiency Location/Instance	Main Entrance, Main Lobby
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


**K211**

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Main Lobby No violations recorded.
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Corridor near Room 324,320,218, Room B32, Exit 4, and others
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Exit 4 No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Corridor near Room 225,217, Rooms B44,B32, 110, and others
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Corridor near Room 225 No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>CLASSROOMS/CORRIDORS/ADMIN SPACES</b>	Inspected
Specialties	Does not Exist
<b>GYMNASIUM</b>	Inspected
Instance on 1st Floor	Inspected
<b>Ceiling</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Fixed Equipment</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	WOOD: DAMAGED/DETERIORATED
Deficiency Location/Instance	Near Entrance, sink, storage
Deficiency Quantity	200
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Entrance No violations recorded.
<b>Seating</b>	
Instance on 1st Floor	Does not Exist
<b>Sliding-folding Partition</b>	
Instance on 1st Floor	Inspected
Condition	3 - Fair
Deficiency	MOVABLE PANELS: DAMAGED
Deficiency Location/Instance	Near center
Deficiency Quantity	160
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>GYMNASIUM</b>	Inspected
<b>Sliding-folding Partition</b>	
Deficiency Photo1	
	Near center
Violations	No violations recorded.
<b>Stage</b>	
Instance on 1st Floor	Does not Exist
<b>Walls</b>	
Instance on 1st Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Near sink
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near sink
Violations	No violations recorded.
<b>Window Curtains/Shades/Blinds</b>	
Instance on 1st Floor	Does not Exist
<b>INTERIOR DOOR HARDWARE</b>	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
<b>INTERIOR GUARDS</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	DETERIORATED/TORN-OUT/MISSING
Deficiency Location/Instance	Stair H/3
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>INTERIOR GUARDS</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair H/3 No violations recorded.
<b>KITCHEN</b>	
Instance on Basement	Inspected
Instance on Basement	Inspected
<b>Ceiling</b>	
Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	METAL PAN: DAMAGED/MISSING
Deficiency Location/Instance	Office
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Office No violations recorded.
<b>Door(s)</b>	
Instance on Basement	Inspected
Condition	3 - Fair
Deficiency	METAL: DETERIORATED DOOR
Deficiency Location/Instance	Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211


Question	Response
----------	----------

**INTERIOR**

**KITCHEN**

**Door(s)**

Deficiency Photo1



Office

Violations

No violations recorded.

**Floor Finish**

Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Near entrance, center, windows, sink
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	



Near sink

Violations

No violations recorded.



**Walls**

Instance on Basement	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Area near storage
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection


K211

Question	Response
<b>INTERIOR</b>	
<b>KITCHEN</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Area near storage No violations recorded.
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Storage
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Storage No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Near Entrance, storage
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near Entrance No violations recorded.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>LIBRARY</b>	Inspected
Instance on 2nd Floor	Inspected
<b>Built-in Furnishing</b>	
Instance on 2nd Floor	Does not Exist
<b>Ceiling</b>	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Floor Finish</b>	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Walls</b>	
Instance on 2nd Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	GYPSUM BOARD: DETERIORATED
Deficiency Location/Instance	Near Windows
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Windows
Violations	No violations recorded.
<b>LOCKER ROOM</b>	Does not Exist
<b>MULTI-PURPOSE ROOM</b>	Does not Exist
<b>SCIENCE DEMO ROOM</b>	Inspected
Instance on Rooms 101, 201, 205	Inspected
Alternative use	Yes
<b>Fixed Equipment</b>	
Instance on Rooms 101, 201, 205	Inspected
Condition	3 - Fair
Deficiency	CABINETRY: MISSING/DAMAGED
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	16
Quantity Uom	L.F.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>SCIENCE DEMO ROOM</b>	
<b>Fixed Equipment</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Entrance
Violations	No violations recorded.
<b>SCIENCE LAB</b>	Inspected
Instance on Room 209	Inaccessible
<b>SCIENCE PREP ROOM</b>	Inspected
Instance on Room 203	Inaccessible
Instance on Room 303	Inspected
Alternative use	Yes
<b>Fixed Equipment</b>	
Instance on Room 303	Inspected
Condition	3 - Fair
Deficiency	CABINETRY: MISSING/DAMAGED
Deficiency Location/Instance	Near Entrance
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near Entrance
Violations	No violations recorded.
<b>SHOWER ROOM</b>	Inspected
Instance on Basement - Boys	Inaccessible
Instance on Basement - Girls	Inaccessible
<b>STAIRS/RAMPS: INTERIOR</b>	Inspected
Do Letter Stair Signs Exist?	Yes

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Partition</b>	Does not Exist
<b>Railings</b>	Inspected
Condition	3 - Fair
Deficiency	METAL: BROKEN BRACKET
Deficiency Location/Instance	Stair A/1
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair A/1 No violations recorded.
<b>Stairs and Landings</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	STONE: BROKEN/MISSING
Deficiency Location/Instance	Stair H3,2,1,Basement
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair H/1 No violations recorded.
Deficiency	STONE: BROKEN/MISSING

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	
<b>Stairs and Landings</b>	
Deficiency Location/Instance	Stair H/2
Deficiency Quantity	10
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
Violations	Stair H/2 No violations recorded.
Deficiency	VINYL TILES: BROKEN/DETERIORATED/MISSING TILES
Deficiency Location/Instance	A/3,Basement, Stair B/Bulkhead, H/3, Basement
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair A/3 No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/MISSING
Deficiency Location/Instance	Stair A/Bulkhead, B/Bulkhead, H/Bulkhead
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>STAIRS/RAMPS: INTERIOR</b>	
<b>Stairs and Landings</b>	
Deficiency Photo1	
Violations	Stair H/Bulkhead No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	GLAZED BLOCK: CRACKS/SPALLING
Deficiency Location/Instance	Stair A/3,1,B/3,2,D/2, and others
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Stair A/3 No violations recorded.
<b>TOILET ROOMS - STAFF</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Room 304,222,124,123,B16, and others
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




K211

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	
<b>Door(s)</b>	
Deficiency Photo1	
Violations	Room 304 No violations recorded.
<b>Floor Finish</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Room 332,138,137,Gymnasium,B16, and others
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 332 No violations recorded.
<b>Stalls</b>	Inspected
Condition	5 - Poor
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Room 332,222,138,137,gymnasium
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	
<b>Stalls</b>	
Deficiency Photo1	
	Room 332
Violations	No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	PLASTER: CRACKS/SPALLING
Deficiency Location/Instance	Rooms 222,138
Deficiency Quantity	20
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 222
Violations	No violations recorded.
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Room 332,138,137,124,Gymnasium, and others
Deficiency Quantity	50
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STAFF</b>	Inspected
Walls	Inspected
Violations	Room 332 No violations recorded.
<b>TOILET ROOMS - STUDENTS</b>	Inspected
<b>Ceiling</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Door(s)</b>	Inspected
Condition	5 - Poor
Deficiency	WOOD: DETERIORATED DOOR
Deficiency Location/Instance	Rooms 220,216,128
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 128 No violations recorded.
Deficiency	WOOD: DAMAGED LOUVER
Deficiency Location/Instance	Rooms 320,316
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 316 No violations recorded.
<b>Floor Finish</b>	Inspected
Condition	3 - Fair

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STUDENTS</b>	Inspected
<b>Floor Finish</b>	
Deficiency	CERAMIC TILE: BROKEN/MISSING TILES
Deficiency Location/Instance	Room 320,316,220,216,128
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 316
Violations	No violations recorded.
<b>Stalls</b>	Inspected
Condition	3 - Fair
Deficiency	RUST - MAJOR
Deficiency Location/Instance	Room 128
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Room 128
Violations	No violations recorded.
<b>Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	CERAMIC TILE: BROKEN/ MISSING
Deficiency Location/Instance	Room 320,316,220,216,128
Deficiency Quantity	40
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>INTERIOR</b>	
<b>TOILET ROOMS - STUDENTS</b>	
<b>Walls</b>	
Deficiency Photo1	
Violations	Room 316 No violations recorded.
<b>LIFE SAFETY</b>	Inspected
<b>F.D. HOLDING AREA</b>	Inspected
Condition	5 - Poor
Deficiency	WINDOWS NOT ADEQUATE
Deficiency Location/Instance	Rooms B3, 301
Deficiency Quantity	60
Quantity Uom	S.F.
Potential Action	INSTALL NEW
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room B3 No violations recorded.
Deficiency	HOLDING AREAS NOT IDENTIFIED
Deficiency Location/Instance	Rooms B3, 301
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	PROVIDE IDENTIFICATION ON EXTERIOR SIDE OF WINDOW
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

**K211**

Question	Response
<b>LIFE SAFETY</b>	
<b>F.D. HOLDING AREA</b>	
Deficiency Photo1	
Violations	Room 301 No violations recorded.
Deficiency	HOLDING AREAS NOT IDENTIFIED
Deficiency Location/Instance	Rooms B3, 311
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	PROVIDE IDENTIFICATION AT DOOR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Room 301 No violations recorded.
<b>STEEL STAIRS</b>	Does not Exist
<b>SITE</b>	Inspected
<b>CONTAINERIZATION</b>	Does not Exist
<b>Drainage System for Asphalt</b>	Does not Exist
<b>Drainage System for Concrete</b>	Inspected
<b>Catch Basins/Manhole - Surrounded by concrete</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Culverts - Concrete Covering</b>	Does not Exist
<b>Drainage System for Soil</b>	Inspected
<b>Catch Basins/Manhole - Surrounded by Soil</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Culverts - Soil Covering</b>	Does not Exist
<b>DRINKING FOUNTAINS</b>	Does not Exist
<b>FENCES</b>	Inspected
Condition	3 - Fair
Deficiency	CHAIN LINK: RUST - MAJOR

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211



Question	Response
<b>SITE</b>	
<b>FENCES</b>	
Deficiency Location/Instance	Near exit 3
Deficiency Quantity	100
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near exit 3
Violations	No violations recorded.
<b>Deficiency</b>	<b>CONCRETE CURB: DAMAGED/DETERIORATED</b>
Deficiency Location/Instance	Along Avenue J, East 100 Street
Deficiency Quantity	55
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Along Avenue J
Violations	No violations recorded.
<b>IRRIGATION SYSTEM</b>	Does not Exist
<b>PAVING</b>	Inspected
<b>Student Non-Use</b>	Inspected
Gravel Exists?	No
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	3 - Fair
<b>Deficiency</b>	<b>DAMAGED/DETERIORATED/MISSING SECTIONS</b>
Deficiency Location/Instance	Near exit 3, exit 10
Deficiency Quantity	150
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3



**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection



K211

Question	Response
<b>SITE</b>	
<b>PAVING</b>	
<b>Student Non-Use</b>	
<b>Concrete</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near exit 3 No violations recorded.
<b>Pavers</b>	Does not Exist
<b>Student Use</b>	Does not Exist
<b>Site Sidewalks &amp; Walkways</b>	Inspected
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Near exit 7, Exit 6
Deficiency Quantity	1,750
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
Violations	Near exit 7 No violations recorded.
<b>Pavers</b>	Does not Exist
<b>DOT Sidewalk</b>	Inspected
<b>Asphalt</b>	Does not Exist
<b>Concrete</b>	Inspected
Condition	4 - Between Fair and Poor
Deficiency	DAMAGED/DETERIORATED/MISSING SECTIONS
Deficiency Location/Instance	Along East 100 Street, East 101 Street, Avenue J
Deficiency Quantity	1,000
Quantity Uom	S.F.

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>SITE</b>	
<b>PAVING</b>	
<b>DOT Sidewalk</b>	
<b>Concrete</b>	
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Along Avenue J
Violations	No violations recorded.
<b>Deficiency</b>	<b>DAMAGED CURBS</b>
Deficiency Location/Instance	Along East 100 Street, East 101 Street, Avenue J
Deficiency Quantity	300
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Along Avenue J
Violations	No violations recorded.
<b>Pavers</b>	Does not Exist
<b>PLAYGROUNDS</b>	Does not Exist
<b>PLAYING SURFACE</b>	Does not Exist
<b>RETAINING WALLS</b>	Inspected
Are there any Retaining Walls 6' OR higher facing public street/sidewalk?	Yes
<b>Condition</b>	3 - Fair
<b>Deficiency</b>	<b>CAST IN PLACE CONCRETE: DETERIORATED CONTROL/EXPANSION JOINT</b>
Deficiency Location/Instance	Near exit 7, exit 6
Deficiency Quantity	30
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection




K211

Question	Response
<b>SITE</b>	
<b>RETAINING WALLS</b>	
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near exit 7
Violations	No violations recorded.
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Near exit 7, exit 9
Deficiency Quantity	30
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near exit 7
Violations	No violations recorded.
<b>SEATING</b>	Does not Exist
<b>SITE WALLS (NOT RETAINING WALLS)</b>	Inspected
Condition	3 - Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	East 100th Street
Deficiency Quantity	80
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
<b>STAIRS/RAMPS: EXTERIOR</b>	Inspected
<b>Railings</b>	Inspected
Condition	3 - Fair
Deficiency	MISSING
Deficiency Location/Instance	Near Exit 7

**NYC Department of Education**  
**Building Condition Assessment Survey 2023 - 2024**

Architectural Inspection

K211

Question	Response
<b>SITE</b>	
<b>STAIRS/RAMPS: EXTERIOR</b>	
<b>Railings</b>	
Deficiency Quantity	10
Quantity Uom	L.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	
	Near exit 7
Violations	No violations recorded.
<b>Site Cheek/flank Walls</b>	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
<b>Stairs/ramps</b>	Inspected
Condition	3 - Fair
Deficiency	CAST IN PLACE CONCRETE: CRACKS/SPALLING - MAJOR
Deficiency Location/Instance	Near exit 7
Deficiency Quantity	70
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	
	Near exit 7
Violations	No violations recorded.
<b>ARTWORK</b>	Inspected
Instance	Interior - Principal's Office - 71163
Instance Photo	

NYC Department of Education  
Building Condition Assessment Survey 2023 - 2024

Architectural Inspection

K211

Question	Response
ARTWORK	Principal's Office
Instance ID	71163
Artwork exist at stated location?	Yes