Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

Asset: BKLYN HS OF THE ARTS (OL S J HL)-K, 345 DEAN STREET, New York, 11217

Inspection I	d Inspection	Туре				Time In		Last Edited
EE : K6	55 Electrical					2023-11	-28 7:47 AM	2024-06-21 10:40 Al
sset Data								
Question					Answer			
Type of Servi	ce				Below Gro	und		
Does Interacti	ve Whiteboard (I	WB) Exist?			Yes			
Water Penetra	tion in Electrical	Room?			No			
Have any Sys	tems/Major Build	ling Components	been upgraded?		Yes			
					Systems:	LAN		
					Years:	2023		
					Systems:	Fire Alarm Syste	em	
					Years:	2022		
					Systems:	Intrusion Alarm Sensor, Panic Sy		l Control Panel, Infrared
					Years:	2017		
					Systems:	System), Gymna	sium (LED Lig	Theater Lighting hting), Most Exit Lights n (Elevator), Telephone
					Years:	2016		
					Systems:	Gymnasium (Pa	rtial Scoreboard)
					Years:	2015		
					Systems:	Interior Fluoresc	ent Lighting, Lo	ocal Sound System
					Years:	2012		
					Systems:	Public Address S	System, IPDVS/	CCTV System
					Years:	2010		·
					Systems:	Security Lights		
					Years:	2009		
					Systems:	Intrusion Alarm	System (Siren/S	Strobe)
					Years:	2005	-	
					Systems:	Molded Case Ci	rcuit Breaker Ty	pe Panel Board
					Years:	1994, 1999, 200	5, 2008, 2023	•
					Systems:		nel Board, Fused	nel, Fused Disconnect l Toggle Switch Type vitchboard
					Years:	1994		
					Systems:	Intrusion Alarm	System (Remo	te Annunciator)
					Years:	2005, 2017		
DEDICATEI) INTERCOMS	IN FIRE RESC	CUE AREAS					
Question					Response			
and/or Holdin	ng Rooms in your	building?	re Rescue Areas,		Yes			
during a f	ire?		hese spaces for use		No		2.245	
Which	spaces do not ha	ve dedicated inte	ercoms?		Rooms 137	7, 140, 210, 232, 30	03, 340	
riority Conditi	on							
Priority Condition Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Status	PhotoImage
No	Fire Alarm System - Components Not Operational	N/A	FIRE ALARM SYSTEM Magnetic Door Holder/Contacto	Corridors by Rooms 325, 303, 225, 201A, 108	Willie Negron	Fireman	Sent to DSF	

Building Condition Assessment Survey 2023 - 2024

ectrical I	nspection	D	munig conu		nent Survey 2	020 2021		K6
fes	Fire Alarm System - Components Not Operational		FIRE ALARM SYSTEM Sprinkler Flow/Air Pressure Switch	Basement by Room B2	Willie Negron	Fireman	Sent to DSF	
pection								
Question					Response	e		
Electrical								
AUDITO	ORIUM				Inspected			
	Instance on 1st Floor	•			Inspected			
House	Lighting				Inspected			
	Does a Chandelier ex	xist?			Yes			
	Instance on 1st Floor	•			Inspected			
Ligh	ting Fixture - Fluore	scent						
	Instance on 1st Floor	•			Does not	Exist		
Ligh	ting Fixture - HID							
	Instance on 1st Floor	•			Does not	Exist		
Ligh	ting Fixture - Incand	escent						
	Instance on 1st Floor	•			Inspected			
Pe	ndant Mounted				Inspected			
	Instance on 1st Floor				Inspected			
-	Condition				3 - Fair			
	Deficiency				No defici	encies recorded	d	
Su	rface Mounted				Does not	Exist		
	Instance on 1st Floor				Does not	Exist		
Re	ecessed Mounted				Does not	Exist		
	Instance on 1st Floor				Does not	Exist		
Ligh	ting Fixture - LED							
	Instance on 1st Floor				Does not	Exist		
Local S	Sound System				Inspected			
	Instance on 1st Floor	•			Inspected	,		
	Installation Year				2012			
	Source of Installation	n			Custodial	Staff		
Conc	lition				3 - Fair			
	Deficiency				No defici	encies recorded	d	
Projec	tion System				Inspected			
	Is the projector on a	cart or installed or	n the ceiling?		Ceiling			
	Instance on 1st Floor	•			Inspected			
Conc	lition					en Good and F		
	Deficiency					encies recorded	đ	
Theate	er Lighting System				Inspected			
	Instance on 1st Floor	•			Inspected			
Dim	ming System							
	Instance on 1st Floor	•			Inspected			
Co	ondition					en Good and F		
	Deficiency ater Lighting				No defici	encies recorded	d	

Theater Lighting

uestion	Response	
AUDITORIUM	··· k · · · · ·	
Theater Lighting System		
Theater Lighting		
Instance on 1st Floor	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Does not Exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier exist?	Yes	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Inspected	
Pendant Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - LED	Does not Exist	
COMPUTER LAB	Inspected	
Instance on Room 304	Inspected	
Power Panel	Yes	
Lighting	Inspected	
Instance on Room 304	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 304	Inspected	
Pendant Mounted	Inspected	
Instance on Room 304	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Room 304	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Room 304	Does not Exist	
Lighting Fixture - HID		
Instance on Room 304	Does not Exist	
Lighting Fixture - Incandescent		

Building Condition Assessment Survey 2023 - 2024

rical Inspection	Despense
estion	Response
COMPUTER LAB	Turner 1
Lighting	Inspected
Lighting Fixture - LED	
Instance on Room 304	Does not Exist
Raceway With Receptacles	Inspected
Instance on Room 304	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
YMNASIUM	Inspected
Instance on 4th Floor	Inspected
Lighting	Inspected
Instance on 4th Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 4th Floor	Does not Exist
Lighting Fixture - HID	
Instance on 4th Floor	Does not Exist
Lighting Fixture - Incandescent	
Instance on 4th Floor	Does not Exist
Lighting Fixture - LED	
Instance on 4th Floor	Inspected
Pendant Mounted	Inspected
Instance on 4th Floor	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Recessed Mounted	Does not Exist
Instance on 4th Floor	Does not Exist
Local Sound System	
Instance on 4th Floor	Inspected
Installation Year	Inspected 2012
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	No deficiencies recorded
Projection System	Does not Exist
Instance on 4th Floor	Does not Exist
Scoreboard	Inspected
Instance on 4th Floor	Inspected
Condition	4 - Between Fair and Poor
Deficiency	NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Theater Lighting System	Does not Exist
Theater Lighting System Instance on 4th Floor	Does not Exist Does not Exist

(P)

Building Condition Assessment Survey 2023 - 2024

uestion	Response	
KITCHEN	Does not Exist	
LIBRARY	Does not Exist	
LOCKER ROOM	Inspected	
Instance on Room 435	Inspected	
Alternative use	Yes	
Lighting	Inspected	
Instance on Room 435	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 435	Inspected	
Pendant Mounted	Does not Exist	
Instance on Room 435	Does not Exist	
Surface Mounted	Inspected	
Instance on Room 435	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Instance on Room 435	Does not Exist	
Lighting Fixture - HID		
Instance on Room 435	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Room 435	Does not Exist	
Lighting Fixture - LED		
Instance on Room 435	Does not Exist	
MULTIPURPOSE ROOM	Does not Exist	
SCIENCE DEMO ROOM	Inspected	
Instance on Room 326	Inspected	
Power Panel Alternative use	Yes No	
Instance on Rooms 324, 325, 327	Inspected	
Power Panel	No	
Alternative use	Yes	
Lighting	Inspected	
Instance on Rooms 324, 325, 327	Inspected	
Instance on Room 326	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 324, 325, 327	Inspected	
Instance on Room 326	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 324, 325, 327	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 326	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 324, 325, 327	Does not Exist	
Instance on Room 326	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Rooms 324, 325, 327	Does not Exist	

(P)

rical Inspection estion	Response	
CIENCE DEMO ROOM	Response	
Lighting Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on Room 326	Does not Exist	
	Dues not Exist	
Lighting Fixture - HID	Deve and Ended	
Instance on Rooms 324, 325, 327	Does not Exist	
Instance on Room 326	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 324, 325, 327	Does not Exist	-
Instance on Room 326	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 324, 325, 327	Does not Exist	
Instance on Room 326	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 324, 325, 327	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 326	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 324, 325, 327	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 326	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 324, 325, 327	Inspected	
Instance on Room 326	Inspected	
Instructor Unit		
Instance on Rooms 324, 325, 327	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 326	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 324, 325, 327	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Instance on Room 326	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Rooms 324, 325, 327	Does not Exist	
Instance on Room 326	Does not Exist	
CIENCE LAB	Inspected	
CIENCE LAB Instance on Rooms 310, 315, 318, 321	Inspected Inspected	

Building Condition Assessment Survey 2023 - 2024

lestion	Response	
SCIENCE LAB		
Power Panel Alternative use	Yes No	
Lighting Instance on Rooms 310, 315, 318, 321	Inspected	
	Inspected	
Lighting Fixture - Fluorescent	T / 1	
Instance on Rooms 310, 315, 318, 321	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	2 - Between Good and Fair	
Deficiency Surface Mounted	No deficiencies recorded	
	Does not Exist Does not Exist	
Instance on Rooms 310, 315, 318, 321		
Recessed Mounted	Does not Exist	
Instance on Rooms 310, 315, 318, 321	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 310, 315, 318, 321	Does not Exist	
Lighting Fixture - Incandescent		
Instance on Rooms 310, 315, 318, 321	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 310, 315, 318, 321	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Inspected	
Instance on Rooms 310, 315, 318, 321	Inspected	
Instructor Unit		
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms 310, 315, 318, 321	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Projection System	Does not Exist	
Instance on Rooms 310, 315, 318, 321	Does not Exist	
SCIENCE PREP ROOM	Inspected	
Instance on Rooms 314, 317	Inspected	
Power Panel Alternative use	No No	

(P)

Building Condition Assessment Survey 2023 - 2024

trical Inspection		K
iestion	Response	
SCIENCE PREP ROOM		
Lighting		
Instance on Rooms 314, 317	Inspected	
Lighting Fixture - Fluorescent		
Instance on Rooms 314, 317	Inspected	
Pendant Mounted	Inspected	
Instance on Rooms 314, 317	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Does not Exist	
Instance on Rooms 314, 317	Does not Exist	
Recessed Mounted	Does not Exist	
Instance on Rooms 314, 317	Does not Exist	
Lighting Fixture - HID		
Instance on Rooms 314, 317	Does not Exist	
·	Does not Exist	
Lighting Fixture - Incandescent	Decement Enter	
Instance on Rooms 314, 317	Does not Exist	
Lighting Fixture - LED		
Instance on Rooms 314, 317	Does not Exist	
Emergency Gas Shut-Off Valve	Inspected	
Instance on Rooms 314, 317	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power	Inspected	
Instance on Rooms 314, 317	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Power Supply	Does not Exist	
Instance on Rooms 314, 317	Does not Exist	
SWIMMING POOL	Does not Exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not Exist	
Lighting Fixture - HID	Does not Exist	
Lighting Fixture - Incandescent	Does not Exist	
Lighting Fixture - LED	Does not Exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	

Deficiency

No deficiencies recorded

Building Condition Assessment Survey 2023 - 2024

uestion	Response
FOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	Inspected
	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not Exist
Lighting Fixture - HID	Does not Exist
Lighting Fixture - Incandescent	Does not Exist
Lighting Fixture - LED	Does not Exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Replacement Quantity	129,000
Replacement Uom	S.F.
Condition	3 - Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not Exist
EMERGENCY GENERATOR SET	Does not Exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Basement - by Electrical Room
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
	PRIORITY 2
Urgency of Action Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
violations	No violations recorded.
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3 - Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	4
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35671705P
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	4th Floor (Staircase B landing, by Room 433), Auditorium
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Deficiency Photo1	No photo recorded
Violations	35671705P
Violations	Instructed

Inspected

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

fical inspection		KUS
estion	Response	
MERGENCY LIGHTING		
Non Battery Pack		
Condition	3 - Fair	
Deficiency	FIXTURE LAMP NOT OPERATIONAL	
Deficiency Location/Instance	Gymnasium	
Deficiency Quantity	3	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 5	
Purpose of Action	LEVEL 4	
Deficiency Photo1	No photo recorded	
Violations	35557770M	
XIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not Exist	
XIT/EMERGENCY LIGHT	Does not Exist	
IRE ALARM SYSTEM		
Replacement Quantity	Inspected 129,000	
Replacement Uom	S.F.	
Bell/Horn	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	-
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	1 - Good	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Inspected	
Condition	3 - Fair	

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

estion	Response
IRE ALARM SYSTEM	
Magnetic Door Holder/Contactor	
Deficiency	CONTACTOR NOT OPERATIONAL
Deficiency Location/Instance	Corridors by Rooms 325, 303, 225, 201A, 108
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Fused Cutout Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not Exist
Main Panel	Inspected
Bell At Panel	Does not Exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	1 - Good
Instance Quantity	1
Instance Quantity Uom	EACH
Instance Manufacturer	Edwards System Technology
Equipment	Fire Alarm Command Center
Model	EST3X
Installation Year	2022
Source of Installation	Custodial Staff
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not Exist
Sub-Panel	Does not Exist
Remote Annunciator	Inspected
Display Monitor	Does not Exist
Panel	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Punch Register	Does not Exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	3 - Fair
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Basement by Room B2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Deficiency Photo1	No photo recorded

K655

uestion	Response
FIRE ALARM SYSTEM	Inspected
Sprinkler Flow/Air Pressure Switch	Inspected
Violations	121233852M
Tamper Flow Switch/Chain	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Inspected
Elevator	Inspected
Condition	2 - Between Good and Fair
Deficiency	No deficiencies recorded
Holding Area	Does not Exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Inspected
Condition	1 - Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not Exist
MOTOR CONTROLLER	Inspected
Motor Control Center	Does not Exist
Motor Starter/Contactor	Inspected
Condition	3 - Fair
Deficiency	MOTOR STARTER PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance	Basement Fan Room (Guidance Supply S4)
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
Variable Frequency Drive	Does not Exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3 - Fair
Deficiency Europe Knife Switch Turne	No deficiencies recorded
Fused Knife Switch Type	Does not Exist
Fused Toggle Switch Type	Inspected
Condition	3 - Fair
Deficiency	No deficiencies recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3 - Fair
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1
Quantity Uom	EACH

Building Condition Assessment Survey 2023 - 2024

Electrical Inspection

trical Inspection	Kt
uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
PUBLIC ADDRESS SYSTEM	Inspected
Replacement Quantity	129,000
Replacement Uom	S.F.
Instance	General Office
Instance Condition	2 - Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	
Installation Year	Quantum Multicom 2010
Source of Installation	Custodial Staff
	CLOCK NOT OPERATIONAL
Deficiency	
Deficiency Location/Instance	Classrooms and Corridors
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Deficiency Photo1	No photo recorded
Violations	No violations recorded.
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Replacement Quantity	129,000
Replacement Uom	S.F.
Installation Year	2010
Source of Installation	Custodial Staff
Condition	3 - Fair
Deficiency	CAMERA NOT OPERATIONAL
Deficiency Location/Instance	
Deneterely Document Instance	Exterior Walls - facing (Dean Street, Pacific Street)
Deficiency Quantity	
-	Exterior Walls - facing (Dean Street, Pacific Street)
Deficiency Quantity	Exterior Walls - facing (Dean Street, Pacific Street) 4
Deficiency Quantity Quantity Uom	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH
Deficiency Quantity Quantity Uom Potential Action	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE
Deficiency Quantity Quantity Uom Potential Action Urgency of Action	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3 No photo recorded No violations recorded.
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Intrusion Alarm System	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3 No photo recorded No violations recorded. Inspected
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Intrusion Alarm System Replacement Quantity	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3 No photo recorded No violations recorded. Inspected 129,000
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Intrusion Alarm System Replacement Quantity Replacement Uom	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3 No photo recorded No violations recorded. Inspected 129,000 S.F.
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Intrusion Alarm System Replacement Quantity Replacement Uom Central Control Panel	Exterior Walls - facing (Dean Street, Pacific Street)4EACHREPLACEPRIORITY 4LEVEL 3No photo recordedNo violations recorded.Inspected129,000S.F.Inspected
Deficiency Quantity Quantity Uom Potential Action Urgency of Action Purpose of Action Deficiency Photo1 Violations Intrusion Alarm System Replacement Quantity Replacement Uom	Exterior Walls - facing (Dean Street, Pacific Street) 4 EACH REPLACE PRIORITY 4 LEVEL 3 No photo recorded No violations recorded. Inspected 129,000 S.F.

iestion	Response	
	Response	
SECURITY		
Intrusion Alarm System Central Control Panel		
Instance Quantity Uom	EACH	
·		
Model Installation Year	Vista-128BPT	
Source of Installation	Custodial Staff	
Deficiency	No deficiencies recorded	
Infrared Sensor		
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch		
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3 - Fair	
Deficiency	SIREN/STROBE NOT ACTIVE	
Deficiency Location/Instance	Corridors by Rooms (443C, 320, 210, 111, 136), Exterior Wall - fac Dean Street	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 4	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
Lighting - Security	Inspected	
Replacement Uom	EACH	
Condition	3 - Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Location/Instance	Building Perimeter	
Deficiency Quantity	8	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 3	
Deficiency Photo1	No photo recorded	
Violations	No violations recorded.	
SERVICE SWITCH	Inspected	
Instance		
Instance Condition	Electrical Room 3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Electrotech	
Equipment	N/A	
Capacity/Size Quantity	4,000	
Capacity/Size UOM	Amps	

etrical Inspection		K
uestion	Response	
SERVICE SWITCH		
Source of Capacity/Size	Nameplate	
Installation Year	1994	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	0	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Instance Manufacturer	Electrotech	
Equipment	N/A	
Capacity/Size Quantity	4,000	
Capacity/Size UOM	Amps Total	
Capacity/Size2 Quantity	4	
Capacity/Size2 UOM	Section(S)	
Source of Capacity/Size	Service Switch Size	
Installation Year	1994	
Source of Installation	Inspector Estimate	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not Exist	
Molded Case Circuit Breaker Type	Does not Exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	2 - Between Good and Fair	
Deficiency	No deficiencies recorded	