Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S. 108 - MAN	HATTAN, 1615 MADISON	AVENUE, MAN	HATTAN, NY,	10029		
Inspectio	n Id Inspection Type				Time	In	Last Edited
	139 ELECTRICAL				2023-	10-12 08:21A	M 2023-11-07 12:59P
sset Data							
Question	l			Answer			
Have any	v Systems/Major Building	Components been upgraded?		Systems: Years:		rium (LED Ligh ks), Exit Lights	ting), Public Address (Battery Pack)
				Systems:			hain), Emergency
				Years:	2022		
				Systems:		tection, Variabl	e Frequency Drives
				Years:	2021 Service Switz	h Switchhoord	Dortial Crown din a
				Systems: Years:	System 2018	n, Swhenboard	Partial Grounding
				Systems:		ing (Except Scie	ence Lab and Auditorium),
				2 jetemer	Most Emerger		on Battery Pack), Public
				Years:	2014		
				Systems:		Projection Syste	m, Local Sound System)
				Years:	2010		
				Systems:		Circuit Breaker	Panel Board
				Years:	2009		
				Systems:		Room 344	
				Years:	2008		
				Systems:	Panel	m System, Eme	ergency Light/Exit Light
				Years:	1998		
Type of S		- E:		Below G	round		
	eractive Whiteboard (IWB netration In Electrical Roo			Yes Yes			
		N FIRE RESCUE AREAS		105			
Question					Response		
-		ance Areas, Fire Rescue Areas, a	nd/or Holding Room		No		
your bı	uilding?						
riority Co	ondition						
Exist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
Last Year?	Category	Description	Affected	Description	Notified	Title	Image
Yes	Water Penetration in Electrical Room	N/A	Electrical Equipment	Electrical Room	Otis Penco	Custodian	
Inspection	ı						
Question	1			Respons	e		
Electrica	al						
ATHL	ETIC FIELD			Does not	exist		
AUDI	FORIUM			Inspected	1		
	Instance on 1st Floor			Inspected	1		
Hous	se Lighting						
	Instance on 1st Floor			Inspected	1		
	Does a Chandelier Ex			No			
Lig	hting Fixture - Fluoresce	nt					
	Instance on 1st Floor			Inspected	1		

Building Condition Assessment Survey 2023-2024

estion	Response	
UDITORIUM		
House Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted	1	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2010	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Does not exist	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	24	
Quantity Uom		
Potential Action	REPLACE-UPGRADE	
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2	

Building Condition Assessment Survey 2023-2024

uestion	Response	
	Kesponse	
AUDITORIUM Theotor Lighting System		
Theater Lighting System Theater Lighting		
Violations	No violations recorded	
CAFETERIA	Inspected	
Instance on 1st Floor	Inspected	
Lighting Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent	hispeeted	
Instance on 1st Floor	Inspected	
Pendant Mounted	hispeeted	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	No deficicieres recorded	
Instance on 1st Floor	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on 1st Floor	Does not exist	
	Does not exist	
Local Sound System Instance on 1st Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1960	
Source of Installation Year	Inspector Estimate	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

	MIIU
Response	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
mspecca	
Does not exist	
Does not exist	
Deer not exist	
Increated	
Inspected	
Does not avist	
Does not exist	
Description of the second seco	
Does not exist	
*	
No deficiencies recorded	
-	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Inspected	
Inspected	
Inspected	
Does not evict	
Does not exist	
Does not exist	
	Does not exist

Building Condition Assessment Survey 2023-2024

rical Inspection	Response	
KITCHEN	Kaponac	
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Does not exist	
LIBRARY	Inspected	
Instance on Room 101	Inspected	
Lighting	inspected	
Instance on Room 101	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 101	Inspected	
Pendant Mounted		
Instance on Room 101	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 101	Does not exist	
Recessed Mounted	Dees not exist	
Instance on Room 101	Does not exist	
Lighting Fixture - HID		
Instance on Room 101	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 101	Does not exist	
Lighting Fixture - LED		
Instance on Room 101	Does not exist	
Raceway With Receptacles	Dees not exist	
Instance on Room 101	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 101	Does not exist	
LOCKER ROOM	Inspected	
Instance on Rooms 304, 350	Inspected	
Alternative Use	Yes	
Lighting	ies	
Instance on Rooms 304, 350	Inspected	
Lighting Fixture - Fluorescent	inspected	
Instance on Rooms 304, 350	Inspected	
Pendant Mounted	inspected	
Instance on Rooms 304, 350	Does not exist	
Surface Mounted		
	Incurated	
Instance on Rooms 304, 350	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted		

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ical Inspection	11	VIIU
iestion	Response	
LOCKER ROOM		
Lighting		
Lighting Fixture - HID		
Instance on Rooms 304, 350	Does not exist	
Lighting Fixture - Incandescent		
Instance on Rooms 304, 350	Does not exist	
Lighting Fixture - LED		
Instance on Rooms 304, 350	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Inspected	
Instance on Room 344	Inspected	
Power Panel?		
	Yes	
Alternative Use	No	
Lighting	T	
Instance on Room 344	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 344	Inspected	
Pendant Mounted		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 344	Does not exist	
Recessed Mounted		
Instance on Room 344	Does not exist	
Lighting Fixture - HID		
Instance on Room 344	Inspected	
Pendant Mounted		
Instance on Room 344	Does not exist	
Surface Mounted		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Room 344	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 344	Does not exist	
Lighting Fixture - LED		
Instance on Room 344	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 344	Inspected	
Instructor Unit		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

		IVIIU
Question	Response	
SCIENCE LAB		
Power Supply		
Instructor Unit		
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Room 344	Does not exist	
Student Unit		
Instance on Room 344	Does not exist	
Projection System		
Instance on Room 344	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Surface Mounted	Inspected 2- Between Good and Fair	
Condition		
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	

Building Condition Assessment Survey 2023-2024

VIIUO

rical Inspection	MIU
uestion	Response
EMERGENCY LIGHTING	
Non Battery Pack	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Exit 6, 7
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35643399Н
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Heat Detector	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Does not exist
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
mounou	1- Good

Building Condition Assessment Survey 2023-2024

Electrical Inspection

item inspection		
Question	Response	
FIRE ALARM SYSTEM		
Main Panel		
Fire Alarm Control Panel (Electronic)		
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards System Technology	
Model	EST 3	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2022	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
GROUNDING SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
INTERCOM SYSTEM	Does not exist	
LAN	Inspected	
Local Distribution Frame (I/LDF)	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected 1- Good	
Condition		
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROL CENTER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
PANEL BOARD	Inspected	
Fused Disconnect Switch Type	Does not exist	
Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
PANEL BOARD	
Molded Case Circuit Breaker Type	
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 107
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 125
Installation Year	1952
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	General Office - Room 107
Deficiency Quantity	88,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
ECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 109
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 128B
Installation Year	1998
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	SENSOR NOT OPERATIONAL
Deficiency Location/Instance	Principal's Office, Kitchen, Nurse's Room
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Under construction
SERVICE SWITCH	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion		Response
SERVICE SW	ИТСН	
Ins	tance Quantity	1
Ins	tance Quantity Uom	EACH
Ma	nufacturer	Electrotech
Equ	upmentId	SS#1 Main Distribution Board
	pacity/Size Quantity	1200
	pacity/Size UOM	Amps
Sou	arce of Capacity/Size	Nameplate
	tallation Year	2018
	arce of Installation Year	Documented
Det	ficiency	No deficiencies recorded
Ins	tance	Electrical Room
Inst	tance Condition	2- Between Good and Fair
Ins	tance Quantity	1
Ins	tance Quantity Uom	EACH
Ma	nufacturer	Electrotech
Equ	aipmentId	SS#2 Spare (A/C)
1	pacity/Size Quantity	400
Cap	bacity/Size UOM	Amps
Sou	arce of Capacity/Size	Nameplate
Inst	tallation Year	2018
Sou	arce of Installation Year	Documented
Det	ficiency	No deficiencies recorded
Ins	tance	Electrical Room
Inst	tance Condition	2- Between Good and Fair
Ins	tance Quantity	1
	tance Quantity Uom	EACH
	nufacturer	Electrotech
	ipmentId	SS#3 Spare
	pacity/Size Quantity	400
	pacity/Size UOM	Amps
-	urce of Capacity/Size	Nameplate
	tallation Year	2018
Sou	arce of Installation Year	Documented
Det	ficiency	No deficiencies recorded
WITCHBO	ARD	Inspected
Number of S		3
	nnect Switch Type	Inspected
	tance	Electrical Room
	tance Condition	2- Between Good and Fair
	tance Quantity	1
	tance Quantity Uom	EACH
	-	Electrotech
	nufacturer	MDP
	aipmentId pacity/Size Quantity	1200
-	pacity/Size Quantity	Amps Total
	pacity/Size 2 Quantity	3
	pacity/Size 2 UOM	S Section(s)
	acty/Size 2 COM	Nameplate
	tallation Year	2018
	irce of Installation Year	Documented
	liciency	No deficiencies recorded
	Switch Type	Does not exist
	e Circuit Breaker Type	Does not exist
Molded Cee		
Molded Cas		Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection

1		
Question	Response	
TELEPHONE SYSTEM		
PBX/Intercom		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	