Building Condition Assessment Survey 2023-2024

Electrical Inspection

Asset:	P.S. 208 (TANDI	EM M185) - MANHATT	AN, 21 WEST 111 S	STREET, MAN	HATTAN, NY,	10026	
Inspection Id	Inspection Type				Time I	n	Last Edited
3177	ELECTRICAL				2024-0	02-13 09:45AM	2024-03-08 02:27PM
sset Data							
Question				Answer			
Have any Syste	ms/Major Building C	Components been upgraded?	,	Systems:	IPDVS/CCTV	System	
	, ,	1 10		Years:	2023		
				Systems:	Intrusion Alarr	n System (Partia	al Remote Annunciator)
				Years:	2022		
				Systems:	Auditorium (L (Raceway with	•	em), Library - Room 260
				Years:	2018		
				Systems:	Security Light	ing	
				Years:	2016, 2000		
				Systems: Years:	Auditorium (R 2015, 2008	ecessed Fluores	cent Lighting)
				Systems:	Interior Lightin Battery Pack)	ng, Partial Emer	gency Lighting (Non
				Years:	2015		
				Systems:	Partial Molded	Case Circuit B	reaker Panel Board
				Years:	2014, 2011, 20	00	
				Systems:	Intrusion Alarr	n System (Panic	Switch)
				Years:	2013		
				Systems:		tem	
				Years:	2012		
				Systems:	Auditorium), F	ire Alarm Syste	Sound System (Except m, Auditorium (Theater
				Years:	Lighting Syste 2008	iii)	
				Systems:	Intrusion Alarr	n System	
				Years:	2001	5	
				Systems:	Emergency Lig	ght/Exit Light Pa vitch Type Panel	anel, Partial Fused Board
				Years:	2000		
Type of Service	2			Below Gr	ound		
	e Whiteboard (IWB)			Yes			
	on In Electrical Roor			No			
	D INTERCOMS II	N FIRE RESCUE AREA	AS		_		
Question Are there any your building		nce Areas, Fire Rescue Area	s, and/or Holding Room		Response No		
riority Condit							
	ority	Condition Description	Component A ffeeted	Location Description	Person(s)	. ,	Photo
	egory	Description	Affected	Description	Notified	Title	Image
No condition re	ecorded						
nspection							
Question				Response			
Electrical							
ATHLETIC	FIELD			Does not	exist		
AUDITORI	UM			Inspected			
In	stance on 1st Floor			Inspected			
House Lig	hting			-			
	stance on 1st Floor			Inspected			
D	oes a Chandelier Exis	st?		No			
Lighting	Fixture - Fluorescer	nt					
T.	stance on 1st Floor			Inspected			

Instance on 1st Floor

Inspected

Building Condition Assessment Survey 2023-2024

estion	Response
UDITORIUM	•
House Lighting	
Lighting Fixture - Fluorescent	
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
	Does not exist
Lighting Fixture - Incandescent	Description interview
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Description int
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
AFETERIA	Inspected
Instance on 1st Floor - East	Inspected
	Inspected
Instance on 1st Floor - West	
Instance on 1st Floor - West	
	Inspected
Instance on 1st Floor - West Lighting	

Building Condition Assessment Survey 2023-2024

Response	
×	
Does not exist	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
Does not exist	
Does not exist	
Inspected	
2- Between Good and Fair	
LIGHTING FIXTURE BALLAST DEFECTIVE	
1	
EACH	
No violations recorded	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Inspected	
mspected	
	Does not exist Does n

Building Condition Assessment Survey 2023-2024

Electrical Inspection

icui Inspeciion		11120
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	4	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED		
COMPUTER LAB	Does not exist	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted	Turner et al	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2008	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Does not exist	
Theater Lighting System		
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

м	2	A	8
TATE T	-	υ	υ.

al Inspection	M2
stion	Response
TCHEN	Inspected
Instance on 1st Floor	Inspected
.ighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
BRARY	Inspected
Instance on Room 208	Inspected
Instance on Room 260	Inspected
.ighting	mpouu
Instance on Room 208	Inspected
Instance on Room 260	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 208	Inspected
	A
Instance on Room 260	Inspected
Pendant Mounted	
Instance on Room 260	Does not exist
Instance on Room 208	Does not exist
Surface Mounted	
Instance on Room 260	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 208	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on Room 260	Does not exist

Building Condition Assessment Survey 2023-2024

Electrical Inspection

linua Inspection		11200
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - HID		
Instance on Room 208	Does not exist	
Instance on Room 260	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 208	Does not exist	
Instance on Room 260	Does not exist	
Lighting Fixture - LED		
Instance on Room 208	Does not exist	
Instance on Room 260	Does not exist	
Raceway With Receptacles		
Instance on Room 208	Does not exist	
Instance on Room 260	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 208	Does not exist	
Instance on Room 260	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Does not exist	
SCIENCE DEMO ROOM	Does not exist	
SCIENCE LAB	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
TOILET ROOM - STUDENT	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY DE STANDET BATTENT FOWER EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

incui Inspection	141200
Question	Response
EMERGENCY LIGHT/EXIT LIGHT PANEL	
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Auditorium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	1st Floor - Corridor, Mechanical Room 210/222
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Inspected
Area Smoke Detector Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded

NYC Department of Education Building Condition Assessment Survey 2023-2024

Response

Electrical Inspection

FIRE ALARM SYSTEM

Question

IKE ALAKIVI 5 I 5 I EM	
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2008
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Tamper Flow Switch/Chain	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
-	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not exist
AN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
JGHTNING PROTECTION	Does not exist
AOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
,	

Building Condition Assessment Survey 2023-2024

Electrical Inspection

iestion	Response
MOTOR CONTROLLER	
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room, Mechanical Room 210/222
Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B11
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	18
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	NO SPARE
Deficiency Location/Instance	Kitchen
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE PANEL BOARD
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	General Office - Room 137
Instance Condition	3- Fair
Instance Quantity	1
	EACH
Instance Quantity Uom	
Model	Rauland TC2100
Installation Year	2008 Decumented
Source of Installation Year	Documented
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Throughout the Building
	6 EACH
Quantity Uom	
Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ricai Inspeciion	MIZU
uestion	Response
PUBLIC ADDRESS SYSTEM	
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	1- Good
Installation Year	2023
Source of Installation Year	Custodial Staff
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	2001
Source of Installation Year	Documented
Deficiency	PANEL NOT CONNECTED TO DOE CENTRAL STATION
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 4
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Lighting - Security Condition	3- Fair
Deficiency	TIME CLOCK NOT OPERATIONAL
Deficiency Location/Instance	
Deficiency Quantity	1st Floor - Electrical Closet By West Cafeteria 1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
	Inspected
SERVICE SWITCH	Electrical Room B11
Instance	3- Fair
Instance Condition	
Instance Quantity	
Instance Quantity Uom	EACH
Manufacturer	Metropolitan
EquipmentId	HTG. EQUIP. P.P
Capacity/Size Quantity	250

Building Condition Assessment Survey 2023-2024

Electrical Inspection

ion	Response	
VICE SWITCH		
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan	
EquipmentId	Kitchen P.P.	
Capacity/Size Quantity	250	
Capacity/Size UOM	Amps	
Source of Capacity/Size	Fuse Size	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Metropolitan	
EquipmentId	M. D. P.#1 Fuse 1000A	
Equipmentia Capacity/Size Quantity	1000	
Capacity/Size UOM		
Source of Capacity/Size	Amps Fuse Size	
Installation Year	1968	
Source of Installation Year	Documented	
Deficiency	BEYOND USEFUL LIFE	
Deficiency Location/Instance	Electrical Room B11	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Instance	Electrical Room B11	
Instance Condition	3- Fair	
Instance Quantity	1	

Building Condition Assessment Survey 2023-2024

	pecuon	N120
Question		Response
SERVICE	SWITCH	
	EquipmentId	M. D. P.#2 Fuse 1200A
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Fuse Size
	Installation Year	1968
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	Electrical Room B11
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 1
		LEVEL 2
	Purpose of Action	
	Violations	No violations recorded
SWITCHI	BOARD	Inspected
Number	of Spares	1
Fused Di	isconnect Switch Type	Inspected
	Instance	Electrical Room B11
	Instance Condition	3- Fair
	Instance Quantity	1
	·	EACH
	Instance Quantity Uom	
	Manufacturer	Metropolitan Electric
	EquipmentId	MDP No. 1
	Capacity/Size Quantity	1200
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	1
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	1968
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	Electrical Room B11
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
	Instance	1st Floor - Electrical Closet By West Cafeteria
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Metropolitan Electric
	EquipmentId	MDP No. 2
	Capacity/Size Quantity	1000
	Capacity/Size UOM	Amps Total
	Capacity/Size OOM Capacity/Size 2 Quantity	Amps rotar 2
	Capacity/Size 2 Quantity Capacity/Size 2 UOM	
		Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	1968
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	1st Floor - Electrical Closet By West Cafeteria
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE

Building Condition Assessment Survey 2023-2024

Electrical Inspection

uestion	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	TELEPHONE NOT OPERATIONAL
Deficiency Location/Instance	1st Floor - West Cafeteria
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE TELEPHONE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
FRANSFORMER	Does not exist