# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:	STATEN ISLAN 10306	ND TECHNICAL HS - STAT	FEN ISLAND, 48	85 CLAWSON S	STREET, STA	ATEN ISLANI	), NY,
Inspection					Time	In	Last Edited
3	353 ELECTRICAL				2024-	-02-20 07:24AN	1 2024-03-19 09:44AN
set Data							
Question				Answer			
Have any S	Systems/Major Building	Components been upgraded?		Systems:	-	st Floor - Local	Sound System, Score
				N/	Board		
				Years:	2024 Listing Sa		
				Systems:	Lighting - Sec 2021, 2002	curity	
				Years: Systems:	Variable Freq	uancy Drive	
				Years:	2021	dency Drive	
				Systems:		d Case Circuit B	reaker Panel Board
				Years:		2002, 2000, 1988	
				Systems:			ceway with Receptacles)
				Years:	2018	(	·····)
				Systems:		ing (Except Scie	nce Rooms 141, 143),
				<u> </u>			on Battery Pack), Exit
					Lights (Batter	ry Pack)	
				Years:	2016		
				Systems:	Intrusion Ala	rm System	
				Years:	2015		
				Systems:		Theater Lighting cy Lights, Fire A	
				Years:	2013	icy Lights, File A	Marin System
				Systems:		h, Switchboard,	Intercom System
				Years:		elephone System	5
				Systems:		ight/Exit Light P	anel
				Years:	2008	0 0	
				Systems:	Science Lab I	Room 143 (Light	ting), Science Prep Room
					141 (Lighting	;)	
				Years:	2007		
				Systems:		System (Auditor	ium)
				Years:	2006		
Type of Ser		) E:		Below Gr	ound		
	active Whiteboard (IWB) etration In Electrical Roo			Yes Yes			
		N FIRE RESCUE AREAS		103			
Question				l	Response		
-	e any Life Rescue Assista	ance Areas, Fire Rescue Areas, a	nd/or Holding Room		Yes		
your buil	0		1		NT.		
	dicated intercoms available h spaces do not have dec	ble in all of these spaces for use	during a fire?		No Rooms: C2_C36	5 242 252 242	Gymnasium 1st Floor,
	-	neared intercoms:			Gymnasium 3rd		Gymnasium 1st Floor,
<i>ority Con</i> tist	Priority	Condition	Component	Location	Person(s)	Person(s)	Photo
	Category	Description	Affected	Description	Notified	Title	Image
s	Water Leaks onto	Water leaks onto Light	Lighting	Boiler Room	Mark	Custodian	
	Electrical Equipment	Fixture	Fixture		Bendit		

Elevator

# Building Condition Assessment Survey 2023-2024

#### **Electrical Inspection**

No	Water Penetration in	Water penetrates through	Electrical	Electrical	Mark	Custodian		
110	Electrical Room	foundation wall.	Equipment	Room	Bendit	Cubicului		-
							ALIN'S A	

Duestion	Response
lectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 1st Floor	Inspected
	nispected
House Lighting Instance on 1st Floor	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	105
Instance on 1st Floor	Inspected
Pendant Mounted	inspected
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 1st Floor	Does not exist
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year	2006
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 1st Floor	Inspected



# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

rical Inspection		<b>K</b> 44
uestion	Response	
AUDITORIUM		
Theater Lighting System		
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CAFETERIA	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted	Inspected	
Instance on Basement	Does not exist	
Surface Mounted	Does not exist	
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	No deficiencies recorded	
Recessed Mounted	T (1	
Instance on Basement	Inspected 2- Between Good and Fair	
Instance Condition		
Deficiency	No deficiencies recorded	-
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	5- Poor	
Installation Year	1980	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action Violations	LEVEL 2	
	No violations recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System	Description int	
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted Condition	Inspected 2- Between Good and Fair	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

icui inspection		
uestion	Response	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
COMPUTER LAB	Inspected	
Instance on Room C56	Inspected	
Power Panel?	No	
Instance on Room 235	Inspected	
Power Panel?	-	
	No	
Instance on Rooms: 237, 259	Inspected	
Power Panel?	Yes	
Lighting		
Instance on Room C56	Inspected	
Instance on Room 235	Inspected	
Instance on Rooms: 237, 259	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room C56	Inspected	
Instance on Room 235	Inspected	
Instance on Rooms: 237, 259	Inspected	
Pendant Mounted		
Instance on Room C56	Does not exist	
Instance on Room 235	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 237, 259	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room C56	Does not exist	
Instance on Room 235	Does not exist	
Instance on Rooms: 237, 259	Does not exist	
Recessed Mounted		
Instance on Room C56	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 235	Does not exist	
Instance on Rooms: 237, 259	Does not exist	
Lighting Fixture - HID		
Instance on Room C56	Does not exist	
Instance on Room 235	Does not exist	
Instance on Rooms: 237, 259	Does not exist	
Lighting Fixture - Incandescent		

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ricui Inspeciion		K44U
Question	Response	
COMPUTER LAB		
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 235	Does not exist	
Instance on Rooms: 237, 259	Does not exist	
Lighting Fixture - LED		
Instance on Room C56	Does not exist	
Instance on Room 235	Does not exist	
Instance on Rooms: 237, 259	Does not exist	
Raceway With Receptacles		
Instance on Room C56	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on Room 235	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 237, 259	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
GYMNASIUM	Inspected	
Instance on 1st Floor	Inspected	
Instance on 3rd Floor	Inspected	-
Lighting		
Instance on 1st Floor	Inspected	
Instance on 3rd Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 3rd Floor	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 3rd Floor	Does not exist	
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 3rd Floor	Inspected	
Instance on 1st Floor	Inspected	
Pendant Mounted	X	
Instance on 3rd Floor	Does not exist	
Instance on 1st Floor	Does not exist	
Surface Mounted		
Instance on 3rd Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on 3rd Floor	Does not exist	
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Installation Year	2024	

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

		N4-
uestion	Response	
GYMNASIUM		
Local Sound System		
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor	Inspected	
Instance Condition	5- Poor	
Installation Year	1980	
Source of Installation Year	Documented	
Deficiency	AMPLIFIER NOT OPERATIONAL	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE SYSTEM	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Projection System		
Instance on 1st Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
Scoreboard		
Instance on 1st Floor	Inspected	
Instance Condition	1- Good	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Does not exist	
Instance on 3rd Floor	Does not exist	
AITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting Instance on Basement		
	Inspected	
Lighting Fixture - Fluorescent	· · · · ·	
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 344	Inspected	
Lighting		
Instance on Room 344	Inspected	

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

ricui inspeciion		K44
Question	Response	
LIBRARY		
Lighting		
Lighting Fixture - Fluorescent		
Instance on Room 344	Inspected	
Pendant Mounted		
Instance on Room 344	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 344	Does not exist	
Recessed Mounted		
Instance on Room 344	Does not exist	
Lighting Fixture - HID		
Instance on Room 344	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 344	Does not exist	
Lighting Fixture - LED		
Instance on Room 344	Does not exist	
Raceway With Receptacles		
Instance on Room 344	Does not exist	
Projection System		
Instance on Room 344	Does not exist	
LOCKER ROOM	Inspected	
Instance on 1st Floor - Boys	Inspected	
Alternative Use	No	
Instance on 3rd Floor - Boys, Rooms C7, C4	Inspected	
Alternative Use	No	
Instance on Room 148 - Girls	Inspected	
Alternative Use	No	
Instance on 3rd Floor - Girls	Inspected	
Alternative Use	No	
Instance on Room 146	Inspected	
Alternative Use	No	
Lighting	110	
Instance on 1st Floor - Boys	Inspected	
Instance on 3rd Floor - Boys, Rooms C7, C4	Inspected	
Instance on Room 148 - Girls	Inspected	
Instance on 3rd Floor - Girls	Inspected	
Instance on Room 146	Inspected	
Lighting Fixture - Fluorescent		
Instance on 3rd Floor - Boys, Rooms C7, C4	Inspected	
Instance on Room 148 - Girls	Inspected	
Instance on 3rd Floor - Girls	Inspected	
Instance on 1st Floor - Boys	Inspected	
Instance on Room 146	Inspected	
Pendant Mounted	mopored	
Instance on 3rd Floor - Boys, Rooms C7, C4	Does not exist	
Instance on Room 148 - Girls	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on 3rd Floor - Girls		
Instance Condition	Inspected 2- Between Good and Fair	
	No deficiencies recorded	
Deficiency	no denciencies recorded	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

tion	Response
	Kesponse
CKER ROOM	
ighting	
Lighting Fixture - Fluorescent	
Pendant Mounted Instance on Room 146	Inspected
Instance Condition	2- Between Good and Fair
	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Deficiency Quantity	3
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on 1st Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor - Boys, Rooms C7, C4	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 148 - Girls	Does not exist
Instance on Telom 140 Girls	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Instance on Room 146	Does not exist
Instance on 1st Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	No deliciencies recorded
Instance on 3rd Floor - Boys, Rooms C7, C4	Does not exist
Instance on Room 148 - Girls	Does not exist
Instance on Teor - Girls	Does not exist
Instance on Room 146	Does not exist
Instance on 1st Floor - Boys	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor - Boys, Rooms C7, C4	Does not exist
Instance on Room 148 - Girls	Does not exist
Instance on 3rd Floor - Girls	Does not exist
Instance on 1st Floor - Boys	Does not exist
Instance on Room 146	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor - Boys, Rooms C7, C4	Does not exist
Instance on Room 148 - Girls	Does not exist
Instance on 3rd Floor - Girls	Does not exist
Instance on 1st Floor - Boys	Does not exist
Instance on Room 146	Does not exist
	Does not exist
Lighting Fixture - LED	Door not avist
Instance on 3rd Floor - Boys, Rooms C7, C4	Does not exist
Instance on Room 148 - Girls	Does not exist
Instance on 3rd Floor - Girls	Does not exist
Instance on 1st Floor - Boys	Does not exist
Instance on Room 146	Does not exist
LTIPURPOSE ROOM	Does not exist
IENCE DEMO ROOM	Inspected

#### Electrical Inspection

ical Inspection		
estion	Response	
CIENCE DEMO ROOM		
Instance on Room 227	Inspected	
Power Panel?	No	
Alternative Use	No	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 227	Inspected	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 227	Inspected	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Pendant Mounted	1	
Instance on Room 227	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	No deficicies recorded	
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Recessed Mounted		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Lighting Fixture - HID		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Lighting Fixture - LED		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 227	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Does not exist	
Power Supply		
Instance on Room 227	Does not exist	
Instance on Rooms: 210, 234, 236, 242	Inspected	
Instructor Unit		
Instance on Rooms: 210, 234, 236, 242	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

icui Inspection	IV <del>1</del>
iestion	Response
SCIENCE DEMO ROOM	
Power Supply	
Meter Demonstration Unit	
Instance on Rooms: 210, 234, 236, 242	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Projection System	
Instance on Room 227	Does not exist
Instance on Rooms: 210, 234, 236, 242	Does not exist
SCIENCE LAB	Inspected
Instance on Room 143	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Rooms: 144, 241	Inspected
Power Panel?	Yes
Alternative Use	No
Lighting	
Instance on Room 143	Inspected
Instance on Rooms: 144, 241	Inspected
Lighting Fixture - Fluorescent	<b>^</b>
Instance on Room 143	Inspected
Instance on Rooms: 144, 241	Inspected
Pendant Mounted	1
Instance on Room 143	Does not exist
Instance on Rooms: 144, 241	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 143	Does not exist
Instance on Rooms: 144, 241	Does not exist
Recessed Mounted	
Instance on Room 143	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms: 144, 241	Does not exist
Lighting Fixture - HID	
Instance on Room 143	Does not exist
Instance on Rooms: 144, 241	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 143	Does not exist
Instance on Rooms: 144, 241	Does not exist
Lighting Fixture - LED	
Instance on Room 143	Does not exist
Instance on Rooms: 144, 241	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 143	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

		N44
Question	Response	
SCIENCE LAB		
Emergency Gas Shut-Off Valve		
Instance on Rooms: 144, 241	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 143	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Rooms: 144, 241	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Power Supply		
Instance on Room 143	Does not exist	
Instance on Rooms: 144, 241	Inspected	
Instructor Unit		
Instance on Rooms: 144, 241	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Meter Demonstration Unit		
Instance on Rooms: 144, 241	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Student Unit		
Instance on Rooms: 144, 241	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 143	Does not exist	
Instance on Rooms: 144, 241	Does not exist	
SCIENCE PREP ROOM	Inspected	
Instance on Room 141	Inspected	
Power Panel?	No	
Alternative Use		
	Yes	
Instance on Room 142	Inspected	
Power Panel?	Yes	
Alternative Use	No	
Instance on Room 239	Inspected	
Power Panel?	No	
Alternative Use	No	
Lighting		
Instance on Room 141	Inspected	
Instance on Room 142	Inspected	
Instance on Room 239	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 141	Inspected	
Instance on Room 142	Inspected	
Instance on Room 239	Inspected	
Pendant Mounted		
Instance on Room 141	Does not exist	
Instance on Room 142	Does not exist	
Instance on Room 239	Inspected	
Instance Condition	2- Between Good and Fair	

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

estion	Response	
CIENCE PREP ROOM		
Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 141	Does not exist	
Instance on Room 142	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Instance on Room 239	Does not exist	
Recessed Mounted		
Instance on Room 141	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 142	Does not exist	
Instance on Room 239	Does not exist	
Lighting Fixture - HID		
Instance on Room 141	Does not exist	
Instance on Room 142	Does not exist	
Instance on Room 239	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 141	Does not exist	
Instance on Room 142	Does not exist	
Instance on Room 239	Does not exist	
Lighting Fixture - LED		
Instance on Room 141	Does not exist	
Instance on Room 142	Does not exist	
Instance on Room 239	Does not exist	
Emergency Gas Shut-Off Valve		
Instance on Room 141	Does not exist	
Instance on Room 142	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Instance on Room 239	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Emergency Shut-Off Power		
Instance on Room 141	Does not exist	
Instance on Room 142	Does not exist	
Instance on Room 239	Does not exist	
Power Supply	Does not exist	
Instance on Room 141	Does not exist	
Instance on Room 142	Inspected	
Instance on Room 239	Inspected	
Instructor Unit	inspected	
Instance on Room 142	Inspected	
Instance Condition	3- Fair	
	No deficiencies recorded	
Deficiency		
Instance on Room 239	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	

#### Electrical Inspection

rical Inspection	K44
Question	Response
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected 3- Fair
Condition	
Deficiency	DOOR PUSH BUTTON NOT OPERATIONAL
Deficiency Location/Instance Deficiency Quantity	Front of the Building
	2
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Boiler Room, Locker Rooms
Deficiency Quantity	9
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Urgency of Action Purpose of Action	PRIORITY 5 LEVEL 2
Purpose of Action	LEVEL 2

#### Electrical Inspection

1
Response
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Storage Room by Electrical Room
2- Between Good and Fair
1
EACH
Ademco
Fire Alarm Communicator
2012
2013
2013 Documented No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

R44
Response
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
Main Entrance Lobby
2- Between Good and Fair
1
EACH
General Electric
EST 2
Fire Alarm Control Panel
2013
Documented
No deficiencies recorded
Does not exist
Does not exist
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
Inspected
Inspected
3- Fair
INTERCOM CABINET NOT OPERATIONAL
Old Elevator - ID #5P70
1
EACH
REPAIR
PRIORITY 5
LEVEL 6
No violations recorded
Does not exist
Inspected
Inspected
3- Fair
No deficiencies recorded

# **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

K44
Response
No deficiencies recorded
Does not exist
Inspected
Does not exist
Inspected
3- Fair
No deficiencies recorded
Inspected
1- Good
No deficiencies recorded
Inspected
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Basement Fan Room, Room inside Cafeteria, 2nd Floor - Fan
Room
4
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Mechanical Room above Library
l
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Does not exist
Inspected
3- Fair
PANEL BOARD BEYOND USEFUL LIFE
Throughout the Building
17
EACH
REPLACE-UPGRADE
PRIORITY 1
LEVEL 2
No violations recorded
Inspected
Main Office - Room 133
4- Between Fair and Poor
1
EACH
Rauland TC4140
1980
Inspector Estimate
Inspector Estimate

## **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

icui Inspeciion	1/4
uestion	Response
PUBLIC ADDRESS SYSTEM	
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	CLOCK NOT OPERATIONAL
Deficiency Location/Instance	Throughout the building
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	SYSTEM DEFECTIVE
Deficiency Location/Instance	Main Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Main Office - Room 133
Deficiency Quantity	165,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
SECURITY	Under construction
IPDVS/CCTV System Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room 133
Instance Condition	2- Between Good and Fair
Instance Quantity	1 EACH
Instance Quantity Uom	
Model	Vista - 128B
Installation Year	2015
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Infrared Sensor	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Panic Switch	Inspected
Condition	3- Fair
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Main Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
	PRIORITY 4
Urgency of Action	
Urgency of Action Purpose of Action	LEVEL 3

#### Electrical Inspection

ical Inspection	R44
uestion	Response
SECURITY	
Intrusion Alarm System	
Remote Annunciator	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	4- Between Fair and Poor
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE
Deficiency Location/Instance	Perimeter of the Building
Deficiency Quantity	33
Quantity Uom	EACH
Potential Action	REPLACE BALLAST
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 3
Violations	No violations recorded
SERVICE SWITCH	Inspected
	-
Instance	Electrical Room 2- Between Good and Fair
Instance Condition	
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	Service Switch #1 4000A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SWITCHBOARD	Inspected
Number of Spares	18
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Electrotech
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded

#### **Building Condition Assessment Survey 2023-2024**

# Electrical InspectionR440QuestionResponseTELEPHONE SYSTEMTELEPHONE SYSTEMStandardConditionCondition3- FairDeficiencyNo deficiencies recordedTRANSFORMERDoes not exist