#### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

Asset:	P.S. 7 - BRONX, 3201 KINGSBRIDGE AVENUE, BRO	ONX, NY, 10463		
Inspection Id	Inspection Type		Time In	Last Edited
1917	ELECTRICAL		2023-12-22 07:54AM	2024-01-16 09:03AM
sset Data				
Question		Answer		
Have any System	ms/Major Building Components been upgraded?	Systems:	Intrusion Alarm System (Except	Panic Switch and
			Siren/Strobe)	
		Years:	2021	
		Systems:	Molded Case Circuit Breaker Par	nel Boards
		Years:	2018, 2008, 2002, 1997, 1988	
		Systems:	Partial Emergency Lighting (Bat	tery Pack), Partial Exit
			Lights (Battery Pack)	
		Years:	2018	
		Systems:	Telephone System, LAN	
		Years:	2016	

Gymnasium (LED Lighting)

Fire Alarm System, Public Address System, Local Sound System (Cafeteria, Gymnasium), Auxiliary Signal/Bell System, Partial Emergency Lighting (Non

Systems: Years:

Systems:

Years: Systems:

Years:

Years: Systems:

Years:

Systems: Years: 2015

2013

2012

2011

Switchboard 2009

Battery Pack) 2014

Security Lights

IPDVS/CCTV System

Systems: Interior Fluorescent Lighting, Auditorium (Local Sound System, Projection System)

	Systems: Emergency Light/Exit Light Panel
	Years: 2001, 1997
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No
DEDICATED INTERCOMS IN FIRE RESCUE AREAS	
Question	Response

Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in No your building?

#### **Priority Condition**

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency Lighting - Not Operational	Batteries for Emergency Light Fixtures are out of order.	Emergency Lighting	Throughout the Building	David Rodriguez	Fireman	No Photo Taken
No	Water Leaks onto Electrical Equipment	Water penetrates through the ceiling onto the MDF equipment.	MDF Room equipment	MDF Room 112	David Rodriguez	Fireman	
Yes	Fire Alarm System - Components Not Operational	Magnetic Door Holders are out of order.	Fire Alarm System - Magnetic Door Holder/Contac tor	Corridor by Rooms: 153 and 355	David Rodriguez	Fireman	No Photo Taken

# NYC Department of Education Building Condition Assessment Survey 2023-2024

### Electrical Inspection

ection	
Question	Response
Nectrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on Basement	Inspected
House Lighting	
Instance on Basement	Inspected
Does a Chandelier Exist?	Yes
Lighting Fixture - Fluorescent	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on Basement	Inspected
Dimming System	
Instance on Basement	Does not exist
Theater Lighting	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
CAFETERIA	Inspected
Instance on Basement	Inspected
Lighting	
Instance on Basement	Inspected

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

	Λυυ
uestion	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Basement	Inspected
Pendant Mounted	
Instance on Basement	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Basement	Does not exist
Recessed Mounted	
Instance on Basement	Does not exist
Lighting Fixture - HID	
Instance on Basement	Does not exist
Lighting Fixture - Incandescent	
Instance on Basement	Does not exist
Lighting Fixture - LED	
Instance on Basement	Does not exist
Local Sound System	
Instance on Basement	Inspected
Instance Condition	3- Fair
Installation Year	2014
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	
Instance on Basement	Does not exist
Theater Lighting System	
Instance on Basement	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Incandescent	
Surface Mounted	
Deficiency Quantity	30
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 314	Inspected
Power Panel?	Yes
Lighting	
Instance on Room 314	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 314	Inspected
Pendant Mounted	1
Instance on Room 314	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 314	Does not exist
Recessed Mounted	
Instance on Room 314	Does not exist
Lighting Fixture - HID	
Instance on Room 314	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 314	Does not exist
Lighting Fixture - LED	
Instance on Room 314	Does not exist
	Does not exist
Raceway With Receptacles Instance on Room 314	Does not exist
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	T
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 2nd Floor	Does not exist

## **Building Condition Assessment Survey 2023-2024**

rical Inspection	Response	
	Kesponse	
GYMNASIUM		
Lighting Lighting Fixture - LED		
Recessed Mounted		
Instance on 2nd Floor	Does not exist	
Local Sound System		
Instance on 2nd Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 2nd Floor	Does not exist	
Scoreboa <u>rd</u>		
Instance on 2nd Floor	Does not exist	
Theater Lighting System		
Instance on 2nd Floor	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Does not exist	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 101/102	Inspected	
Lighting		
Instance on Room 101/102	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 101/102	Inspected	
Pendant Mounted		
Instance on Room 101/102	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 101/102	Does not exist	
Recessed Mounted		
Instance on Room 101/102	Does not exist	
Lighting Fixture - HID		
Instance on Room 101/102	Does not exist	
Lighting Fixture - Incandescent		

## **Building Condition Assessment Survey 2023-2024**

estion	Response	
IBRARY	. <b>I</b>	
Lighting		
Lighting Fixture - Incandescent		
Instance on Room 101/102	Inspected	
Pendant Mounted	·	
Instance on Room 101/102	Does not exist	
Surface Mounted		
Instance on Room 101/102	Does not exist	
Recessed Mounted		
Instance on Room 101/102	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	2	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Lighting Fixture - LED		
Instance on Room 101/102	Does not exist	
Raceway With Receptacles		
Instance on Room 101/102	Inspected	
Instance Condition	3- Fair	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Room 101/102	Does not exist	
OCKER ROOM	Inspected	
Instance on Room 299	Inspected	
Alternative Use	Yes	
Lighting		
Instance on Room 299	Inspected	
Lighting Fixture - Fluorescent		
Instance on Room 299	Does not exist	
Lighting Fixture - HID		
Instance on Room 299	Does not exist	
Lighting Fixture - Incandescent		
Instance on Room 299	Inspected	
Pendant Mounted	1	
Instance on Room 299	Inspected	
Instance Condition	3- Fair	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE	
Deficiency Quantity	6	
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on Room 299	Does not exist	
Recessed Mounted		
Instance on Room 299	Does not exist	
Lighting Fixture - LED		
Instance on Room 299	Does not exist	
IULTIPURPOSE ROOM	Does not exist	

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

uestion	Response
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
	Does not exist
SWIMMING POOL	
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected 3- Fair
Condition	No deficiencies recorded
Deficiency	
Surface Mounted	Inspected 2. Fair
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	16
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
FOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	8
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Does not exist

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

icai Inspection	Λυ
uestion	Response
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	5- Poor
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	22
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	35672745Y
Non Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	2- Between Good and Fair
Deficiency	FIXTURE NOT OPERATIONAL
Deficiency Location/Instance	Corridors, Gymnasium and Cafeteria
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35672745Y
Non Battery Pack	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	Does not exist
	Inspected
FIRE ALARM SYSTEM	Inspected
Bell/Horn Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
	No deficiencies recorded
Deficiency	Inspected
Manual Pull Station Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected 2- Between Good and Fair
Condition	
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Inspected
Condition	2- Between Good and Fair

## **Building Condition Assessment Survey 2023-2024**

### Electrical Inspection

Δι
Response
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
3- Fair
CONTACTOR NOT OPERATIONAL
Corridor by Rooms: 153 and 355
4
EACH
REPLACE
PRIORITY 5
LEVEL 6
No violations recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Inspected
Does not exist
Inspected
Vestibule by Exit 7
2- Between Good and Fair
1
EACH
Fire Control Instruments
E3 Series
Fire Alarm Control Panel
2014
Documented
No deficiencies recorded
Does not exist
Does not exist
Inspected
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
2- Between Good and Fair
No deficiencies recorded
Does not exist
Does not exist
Inspected
2- Between Good and Fair
No deficiencies recorded
Inspected
3- Fair
No deficiencies recorded
No deficiencies recorded Does not exist

## **Building Condition Assessment Survey 2023-2024**

### **Electrical Inspection**

ricai Inspeciion		<b>AUU</b>
Question	Response	
LAN		
Local Distribution Frame (I/LDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Main Equipment Rack (MDF)	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
LIGHTNING PROTECTION	Does not exist	
MOTOR CONTROLLER	Inspected	
MOTOR CONTROLLER	Does not exist	
MOTOR STARTER/CONTACTOR	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Variable Frequency Drive	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
	Inspected	
PANEL BOARD	Does not exist	
Fused Disconnect Switch Type Fused Knife Switch Type	Does not exist	
Fused Toggle Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
PUBLIC ADDRESS SYSTEM	Inspected	
Instance	Room 115A	
Instance Condition	2- Between Good and Fair	
	1	
Instance Quantity	EACH	
Instance Quantity Uom		
Model	Biamp MPA250 2014	
Installation Year Source of Installation Year	2014 Documented	
Deficiency	No deficiencies recorded	
SECURITY	Inspected	
IPDVS/CCTV System		
Condition Installation Year	2- Between Good and Fair	
Source of Installation Year	2012 Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Custodian's Office	
Instance Condition	1- Good	
Instance Quantity	1	
	EACH	
Instance Quantity Uom Model	Vista 128BPT	
	2021	
Installation Year Source of Installation Year	2021 Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	l-Good	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	

# NYC Department of Education **Building Condition Assessment Survey 2023-2024**

Response	
Inspected	
-	
-	
-	
No deficiencies recorded	
Inspected	
Electrical Room	
3- Fair	
1	
EACH	
Royal Switchboard Co.	
N/A	
1600	
Amps	
-	
1965	
Documented	
BEYOND USEFUL LIFE	
Electrical Room	
1	
EACH	
REPLACE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Inspected	
2	
Inspected	
Electrical Room	
2- Between Good and Fair	
1	
-	
•	
Documented	
No deficiencies recorded	
7. Retween Good and Hair	
2- Between Good and Fair No deficiencies recorded	
	1- Good         No deficiencies recorded         Inspected         3- Fair         No deficiencies recorded         Inspected         2- Between Good and Fair         No deficiencies recorded         Inspected         2- Between Good and Fair         No deficiencies recorded         Inspected         Electrical Room         3- Fair         1         EACH         Royal Switchboard Co.         N/A         1600         Amps         Nameplate         1965         Documented         BEYOND USEFUL LIFE         Electrical Room         1         EACH         REPLACE         PRIORITY 1         LEVEL 2         No violations recorded         Inspected         2         Inspected         2         No violations recorded         Inspected         2         Between Good and Fair         1         EACH         Gallagher Switchboard Co.         N/A         1600         Amps

## **Building Condition Assessment Survey 2023-2024**

Dunning Condition Assessment Survey 2023-2024			
trical Inspection		X00'	
Question	Response		
TELEPHONE SYSTEM			
Standard			
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		
TRANSFORMER	Does not exist		