Building Condition Assessment Survey 2023-2024

Electrical Inspection

| Asset: | NEW SCH FOR ARTS AND SCIENCE - BRONX, 96 | 5 LONGWOOD AVEN | NUE, BRONX, NY, 10459 | |
|-----------------|--|-----------------|--|-----------------------|
| Inspection Id | Inspection Type | | Time In | Last Edited |
| 3160 | ELECTRICAL | | 2024-02-12 09:02AM | 2024-05-24 09:36AN |
| set Data | | | | |
| Question | | Answer | | |
| Have any Syste | ems/Major Building Components been upgraded? | Systems: | Partial LAN (IDF) | |
| | | Years: | 2023 | |
| | | Systems: | IPDVC/CCTV System, Cafeteria Bathrooms (Fluorescent Lighting | |
| | | Years: | 2021 | |
| | | Systems: | Emergency Lighting (Battery Pac | ck) |
| | | Years: | 2018, 2013 | |
| | | Systems: | Partial LAN (MDF), Security Lig | ghting |
| | | Years: | 2018 | |
| | | Systems: | Interior Fluorescent Lighting (exe Lab Rooms - 301, 302, Science F Lights (Battery Pack) | |
| | | Years: | 2013 | |
| | | Systems: | Molded Case Circuit Breaker Par Switch | nel Boards, Service |
| | | Years: | 2007, 1992 | |
| | | Systems: | Kitchen, Science Lab Rooms (30 Room 302A | 1, 302), Science Prep |
| | | Years: | 2007 | |
| | | Systems: | Public Address System, Local So (Cafeteria), Intrusion Alarm System | |
| | | Years: | 2004 | |
| | | Systems: | Fire Alarm System, Emergency I | .ight/Exit Panel |
| | Years: | 2003 | | |
| | | Systems: | Switchboard, Intrusion Alarm Sy | stem |
| | | Years: | 1992 | |
| Type of Service | e | Below Gr | ound | |
| Does Interactiv | ve Whiteboard (IWB) Exist? | Yes | | |
| Water Penetrat | ion In Electrical Room? | No | | |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question Response Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in No your building?

Priority Condition

| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo |
|------------|----------------------|-------------|-----------|-------------|-----------|-----------|-------|
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image |
| No condit | tion recorded | | | | | | |
| Inspection | ! | | | | | | |
| Question | | | | Response | | | |
| Electrica | 1 | | | | | | |
| ATHLI | ETIC FIELD | | | Does not | exist | | |
| AUDIT | ORIUM | | | Does not | exist | | |
| CAFE | ΓERIA | | | Inspected | | | |
| | Instance on Baser | ment | | Inspected | | | |
| Light | ing | | | | | | |
| | Instance on Baser | ment | | Inspected | | | |
| Lig | hting Fixture - Fluo | rescent | | | | | |
| | Instance on Baser | ment | | Inspected | | | |
| P | endant Mounted | | | | | | |
| | Instance on Baser | ment | | Does not | exist | | |
| S | urface Mounted | | | | | | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | | AUC |
|---|--------------------------|-----|
| uestion | Response | |
| CAFETERIA | | |
| Lighting | | |
| Lighting Fixture - Fluorescent | | |
| Surface Mounted | | |
| Instance on Basement | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Basement | Does not exist | |
| Local Sound System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| Installation Year | 2004 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Projection System | | |
| Instance on Basement | Inspected | |
| Instance Condition | 1- Good | |
| Is the projector on a cart or installed on the ceiling? | Ceiling | |
| Deficiency | No deficiencies recorded | |
| Theater Lighting System | | |
| Instance on Basement | Does not exist | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected | |
| Lighting | Inspected | |
| Does a Chandelier Exist? | No | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Does not exist | |
| Recessed Mounted | Does not exist | |
| COMPUTER LAB | Inspected | |
| Instance on Room 102 | Inspected | |
| Power Panel? | | |
| | No | |
| Instance on Room 111 | Inspected | |

Building Condition Assessment Survey 2023-2024

| estion | Response | |
|----------------------------------|-------------------------------------|--|
| COMPUTER LAB | 1 | |
| Lighting | | |
| Instance on Room 102 | Inspected | |
| Instance on Room 111 | Inspected | |
| Lighting Fixture - Fluorescent | Å | |
| Instance on Room 102 | Inspected | |
| Instance on Room 111 | Inspected | |
| Pendant Mounted | A | |
| Instance on Room 102 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 111 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Does not exist | |
| Raceway With Receptacles | | |
| Instance on Room 102 | Does not exist | |
| Instance on Room 111 | Does not exist | |
| SYMNASIUM | Does not exist | |
| AITCHEN | Inspected | |
| Instance on Basement | Inspected | |
| | Inspected | |
| Lighting Instance on Basement | Inspected | |
| Lighting Fixture - Fluorescent | inspected | |
| Instance on Basement | Inspected | |
| Pendant Mounted | inspected | |
| Instance on Basement | Does not exist | |
| Surface Mounted | | |
| Instance on Basement | Does not exist | |
| Recessed Mounted | Does not exist | |
| Instance on Basement | Inspected | |
| Instance Condition | 3- Fair | |
| | 3- rair No deficiencies recorded | |
| Deficiency | ino deliciencies recorded | |
| Lighting Fixture - HID | Door nott | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |

Building Condition Assessment Survey 2023-2024

| uestion | Response | |
|--|---------------------------------------|--|
| | Kesponse | |
| KITCHEN | | |
| Lighting Lighting Fixture - LED | | |
| Instance on Basement | Does not exist | |
| | Does not exist | |
| LIBRARY | | |
| LOCKER ROOM | Does not exist | |
| MULTIPURPOSE ROOM | Inspected | |
| Instance on Basement | Inspected | |
| Lighting | | |
| Instance on Basement | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Basement | Inspected | |
| Pendant Mounted | | |
| Instance on Basement | Inspected 2- Between Good and Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Basement | Inspected 2- Between Good and Fair | |
| Instance Condition | | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - Incandescent | - | |
| Instance on Basement | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Basement | Does not exist | |
| Local Sound System | | |
| Instance on Basement | Does not exist | |
| Projection System Instance on Basement | Does not exist | |
| | Does not exist | |
| Theater Lighting System Instance on Basement | Does not exist | |
| SCIENCE DEMO ROOM | Does not exist | |
| | | |
| SCIENCE LAB | Inspected | |
| Instance on Room 301 | Inspected | |
| Power Panel? | Yes | |
| Alternative Use | Yes | |
| Instance on Room 302 | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Lighting | | |
| Instance on Room 301 | Inspected | |
| Instance on Room 302 | Inspected | |
| Lighting Fixture - Fluorescent | - · · | |
| Instance on Room 301 | Inspected | |
| Instance on Room 302 | Inspected | |
| Pendant Mounted | | |
| Instance on Room 301 | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Instance on Room 302 | Inspected | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | AU. |
|--------------------------|---|
| Response | |
| | |
| | |
| | |
| | |
| 3- Fair | |
| No deficiencies recorded | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| | |
| Inspected | |
| Inspected | |
| | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| Inspected | |
| 3- Fair | |
| No deficiencies recorded | |
| | |
| Does not exist | |
| Does not exist | |
| | |
| Does not exist | |
| | |
| | |
| | |
| Does not exist | |
| | 3- Fair No deficiencies recorded Does not exist No deficiencies recorded Inspected 3- Fair No deficiencies recorded Inspected |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| rical Inspection | | X039 |
|---|--------------------------|------|
| Question | Response | |
| SCIENCE LAB | | |
| Projection System | | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| SCIENCE PREP ROOM | Inspected | |
| Instance on Room 302A | Inspected | |
| Power Panel? | No | |
| Alternative Use | No | |
| Lighting | | |
| Instance on Room 302A | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Room 302A | Inspected | |
| Pendant Mounted | | |
| Instance on Room 302A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 302A | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 302A | Does not exist | |
| Lighting Fixture - HID | Dous not exist | |
| Instance on Room 302A | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Instance on Room 302A | Does not exist | |
| | Does not exist | |
| Lighting Fixture - LED Instance on Room 302A | Does not exist | |
| Emergency Gas Shut-Off Valve | Does not exist | |
| Instance on Room 302A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Emergency Shut-Off Power | | |
| Instance on Room 302A | Inspected | |
| Instance Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Power Supply | No deficiencies recorded | |
| Instance on Room 302A | Does not exist | |
| | Does not exist | |
| SWIMMING POOL | | |
| TOILET ROOM - STAFF | Inspected | |
| Lighting | Inspected Inspected | |
| Lighting Fixture - Fluorescent | * | |
| Pendant Mounted | Does not exist | |
| Surface Mounted | Inspected | |
| Condition | 1- Good | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Does not exist | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| TOILET ROOM - STUDENT | Inspected | |
| Lighting | Inspected | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 1- Good | |
| | | |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|------------------------------------|--|
| TOILET ROOM - STUDENT | |
| Lighting | |
| Lighting Fixture - Fluorescent | |
| Pendant Mounted | |
| Deficiency | No deficiencies recorded |
| Surface Mounted | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| Recessed Mounted | Does not exist |
| Lighting Fixture - HID | Does not exist |
| Lighting Fixture - Incandescent | Does not exist |
| Lighting Fixture - LED | Does not exist |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected |
| Condition | 5- Poor |
| Deficiency | BELL TRANSFORMER PANEL NOT OPERATIONAL |
| Deficiency Location/Instance | Electrical Room Sub Basement |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE PANEL |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist |
| EMERGENCY GENERATOR SET | Does not exist |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| EMERGENCY LIGHTING | Inspected |
| | Inspected |
| Battery Pack Condition | 2- Between Good and Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Near Room 204A, Exit 1D |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Non Battery Pack | Does not exist |
| EXIT LIGHT | Inspected |
| Battery Pack | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | BATTERY NOT OPERATIONAL |
| Deficiency Location/Instance | Near Room 302, Outside Cafeteria, |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE BATTERY |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Deficiency | FIXTURE NOT OPERATIONAL |
| Deficiency Location/Instance | Basement Exit 2 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | A0 |
|---------------------------------------|---------------------------------------|
| uestion | Response |
| FIRE ALARM SYSTEM | |
| Sub-Panel | |
| Fire Alarm Control Panel (Electronic) | Inspected |
| Instance | Main Entrance Lobby |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| Model | PAD-3 |
| EquipmentId | F.A Strobe Panel |
| Installation Year | 2003 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 5- Poor |
| Deficiency | PRINTER NOT OPERATIONAL |
| Deficiency Location/Instance | Room B-15 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| NTERCOM SYSTEM | Does not exist |
| | |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Inspected 2- Between Good and Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| Main Equipment Rack (MDF) | Inspected |
| Condition | 1- Good |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not exist |
| MOTOR CONTROLLER | Inspected |
| MOTOR CONTROL CENTER | Does not exist |
| MOTOR STARTER/CONTACTOR | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Variable Frequency Drive | Does not exist |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| | Δυ |
|----------------------------------|--------------------------------|
| uestion | Response |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Does not exist |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Inspected |
| Condition | 3- Fair |
| Deficiency | PANEL BOARD BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Room B-14 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE-UPGRADE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 2 |
| Violations | No violations recorded |
| Molded Case Circuit Breaker Type | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Instance | MDF Room B6 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Biamp MPA250 |
| Installation Year | 2004 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Condition | 1- Good |
| Installation Year | 2021 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | Room B15 |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | |
| Installation Year | Capricorn CEI-8M 1992 |
| Source of Installation Year | Documented |
| Deficiency | BEYOND USEFUL LIFE |
| Deficiency Location/Instance | Room B15 |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 1 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Infrared Sensor | Inspected |
| Condition | 3- Fair |
| | No deficiencies recorded |
| Deficiency | |
| Panic Switch | Inspected |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |

Building Condition Assessment Survey 2023-2024

| uestion | Response |
|---------------------------------------|--|
| SECURITY | 1 |
| Intrusion Alarm System | |
| Remote Annunciator | |
| Condition | 3- Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 3- Fair |
| | No deficiencies recorded |
| Deficiency | |
| Lighting - Security | |
| Condition | 2- Between Good and Fair |
| Deficiency | LIGHTING FIXTURE PHOTOCELL NOT OPERATIONAL |
| Deficiency Location/Instance | Near Exit 6 and 8 |
| Deficiency Quantity | 3 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 3 |
| Purpose of Action Violations | LEVEL 3 No violations recorded |
| | |
| SERVICE SWITCH | Inspected |
| Instance | Sub Basement - Electrical Room |
| Instance Condition | 3- Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | General Electric |
| EquipmentId | Main Switch |
| Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 1992 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Instance | Sub Basement - Electrical Room |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | Siemens |
| | Main Switch |
| EquipmentId Capacity/Size Quantity | 800 |
| Capacity/Size UOM | Amps |
| Source of Capacity/Size | Nameplate |
| Installation Year | 2007 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| | Inspected |
| SWITCHBOARD | 0 |
| Number of Spares | Inspected |
| Fused Disconnect Switch Type | |
| Instance | Sub Basement - Electrical Room 3- Fair |
| Instance Condition | |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Manufacturer | General Electric |
| EquipmentId | N/A |
| Capacity/Size Quantity | 1200 |
| Capacity/Size UOM | Amps Total |
| Capacity/Size 2 Quantity | 1 |
| | |

Building Condition Assessment Survey 2023-2024

Electrical Inspection

| Question | Response | |
|----------------------------------|--------------------------|--|
| SWITCHBOARD | | |
| Fused Disconnect Switch Type | | |
| Capacity/Size 2 UOM | Section(s) | |
| Source of Capacity/Size | Nameplate | |
| Installation Year | 1992 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| Fused Knife Switch Type | Does not exist | |
| Molded Case Circuit Breaker Type | Does not exist | |
| TELEPHONE SYSTEM | Inspected | |
| PBX/Intercom | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| Standard | Inspected | |
| Condition | 3- Fair | |
| Deficiency | No deficiencies recorded | |
| TDANSEODMED | Does not exist | |

TRANSFORMER

Does not exist