Building Condition Assessment Survey 2023-2024

Asset:	P.S. 73 - BRONX	, 1020 ANDERSON AVI	ENUE, BRONX, N	Y, 10452			
Inspection Id	Inspection Type				Time l	ĺn .	Last Edited
3244	4 ELECTRICAL				2024-0	02-15 09:14AM	2024-03-08 02:40P
set Data							
Question				Answer			
Have any Syst	tems/Major Building C	omponents been upgraded?		Systems:	LAN		
				Years:	2022		
				Systems:	Partial Molded	l Case Circuit B	reaker Panel Board
				Years:		007, 2000, 1994	
				Systems:	Security Light	ing	
				Years:	2021	1. (D.)	1) B 2 1 B
				Systems:	Lights (Non B		ck), Partial Emergency
				Years:	2019	attery rack)	
				Systems:		attery Pack), Gy	mnasiums (LED
				•	Lighting)		`
				Years:	2017		
				Systems:	IPDVS/CCTV	System	
				Years:	2015		
				Systems:			ystem Except (Siren,
					Room 313	r), Telephone Sy	stem, Science Lab
				Years:	2014		
				Systems:		n System (Infrai	red Sensor)
				Years:	2010		
				Systems:	Service Switch	n, Switchboard	
				Years:	2007		
				Systems:	Interior Lighti	ng	
				Years:	2004		
				Systems:	Emergency Li	ght/Exit Light Pa	anel
				Years:	2001		
				Systems:		ystem (Cafeteria	a, Gymnasiums)
				Years:	1996		
Type of Service		F : 49		Below Gr	round		
	ve Whiteboard (IWB) l tion In Electrical Room			Yes No			
		FIRE RESCUE AREA	S	INO			
Question	DIVIERCOMS II	TIKE RESCUE AREA			Response		
-	y Life Rescue Assistan	ice Areas, Fire Rescue Areas	s, and/or Holding Rooi		No		
your buildin							
iority Condi							
	iority itegory	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No condition i		Description	Ameticu	Description	rouncu	11110	
nspection							
Question				Response	<u>.</u>		
Electrical				жэронж	-		
ATHLETIC	C FIELD			Does not	exist		
AUDITOR				Inspected			
_	nstance on 1st Floor			Inspected			
House Lig				mspecieu	•		
_	nstance on 1st Floor			Inspected			
	Does a Chandelier Exis	t?		No			
	g Fixture - Fluorescen			*			

Building Condition Assessment Survey 2023-2024

uestion	Response	
AUDITORIUM	2117-	
House Lighting		
Lighting Fixture - Fluorescent		
Pendant Mounted		
Instance on 1st Floor	Does not exist	
Surface Mounted	DOGS HOT CAIST	
Instance on 1st Floor	Inspected	
	2- Between Good and Fair	
Instance Condition	No deficiencies recorded	
Deficiency	No deliciencies recorded	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Lighting Fixture - HID		
Instance on 1st Floor	Does not exist	
Lighting Fixture - Incandescent		
Instance on 1st Floor	Does not exist	
Lighting Fixture - LED		
Instance on 1st Floor	Inspected	
Pendant Mounted		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	LIGHTING FIXTURE BALLAST DEFECTIVE	
Deficiency Quantity	7	
Quantity Uom	EACH	
Potential Action	REPLACE BALLAST	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	
Local Sound System		
Instance on 1st Floor	Inspected	
Instance Condition	3- Fair	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on 1st Floor	Inspected	_
Instance Condition	2- Between Good and Fair	
Is the projector on a cart or installed on the ceiling?	Ceiling	
Deficiency	No deficiencies recorded	
Theater Lighting System		
Instance on 1st Floor	Inspected	
Dimming System		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Theater Lighting		
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Deficiency	Inspected	

Inspected

Instance on 1st Floor

Building Condition Assessment Survey 2023-2024

Electrical Inspection	X073
Question	Response

Question	Response
CAFETERIA	
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Recessed Mounted	The deficiences recorded
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	DOCS HOT CAIST
-	Does not exist
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	Does not exist
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Description of the second
Instance on 1st Floor	Does not exist
Local Sound System	Y 1
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Installation Year Source of Installation Year	1996 Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Cafeteria-1st Floor
Deficiency Quantity	Calcteria-1st Ploof
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
	Inspected
Surface Mounted Condition	3- Fair
	No deficiencies recorded
Deficiency	
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Inspected
Instance on Room 414	Inspected

Building Condition Assessment Survey 2023-2024

Electrical Inspection		X073
Question	Response	
COMPUTER LAB		
Power Panel?	No	

Question	Response
COMPUTER LAB	
Power Panel?	No
Lighting	
Instance on Room 414	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 414	Inspected
Pendant Mounted	
Instance on Room 414	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on Room 414	Does not exist
Recessed Mounted	
Instance on Room 414	Does not exist
Lighting Fixture - HID	
Instance on Room 414	Does not exist
Lighting Fixture - Incandescent	Does not exist
Instance on Room 414	Does not exist
Lighting Fixture - LED	Does not exist
Instance on Room 414	Does not exist
	DOCS HOT CAIST
Raceway With Receptacles Instance on Room 414	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
GYMNASIUM	Inspected
Instance on 3rd Floor	Inspected
Instance on 5th Floor	Inaccessible
Lighting	
Instance on 3rd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - HID	
Instance on 3rd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 3rd Floor	Does not exist
Lighting Fixture - LED	
Instance on 3rd Floor	Inspected
Pendant Mounted	
Instance on 3rd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Surface Mounted	
Instance on 3rd Floor	Does not exist
Recessed Mounted	
Instance on 3rd Floor	Does not exist
Local Sound System	
Instance on 3rd Floor	Inspected
Instance Condition	3- Fair
Installation Year	1996
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Gymnasium-3rd Floor
Deficiency Quantity	1 FACH
Quantity Uom	EACH

Building Condition Assessment Survey 2023-2024

Response	
*	
REPLACE	
PRIORITY 1	
LEVEL 2	
No violations recorded	
Does not exist	
Does not exist	
Does not exist	
Inspected	
1	
Inspected	
-	
Inspected	
•	
Inspected	
3- Fair	
100 001101101101101101101101101101101101	
Does not exist	
Door not arrist	
Does not exist	
Door not arrist	
Does not exist	
De se met seist	
Inspected	
Inspected	
Inspected	
No deficiencies recorded	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
	REPLACE PRIORITY 1 LEVEL 2 No violations recorded Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected Does not exist Inspected Inspected Does not exist Does not exist Does not exist Does not exist Inspected Inspected Inspected Inspected Inspected Does not exist Does not exist

Building Condition Assessment Survey 2023-2024

ist	
ist	
ist	
I	
ist	
Good and Fair	
cies recorded	
ist	
ist	
ist	
ist	
Good and Fair	
cies recorded	
ist	
ist	
ist	
ist	

Power Supply

Building Condition Assessment Survey 2023-2024

neu inspection		A075
Question	Response	
SCIENCE LAB		
Power Supply		
Instance on Room 313	Does not exist	
Projection System		
Instance on Room 313	Does not exist	
SCIENCE PREP ROOM	Does not exist	
SWIMMING POOL	Does not exist	
TOILET ROOM - STAFF	Inspected	
Lighting	Inspected	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - Incandescent Lighting Fixture - LED	Does not exist	
	Inspected	
TOILET ROOM - STUDENT	Inspected	
Lighting Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
<u>-</u>	Inspected	
Surface Mounted Condition	3- Fair	
-	No deficiencies recorded	
Deficiency	Does not exist	
Recessed Mounted	Does not exist	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist Does not exist	
Lighting Fixture - LED		
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	
Non Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

ical Inspection	X07
uestion	Response
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Under construction
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
NTERCOM SYSTEM	Does not exist
LAN	Inspected
	Inspected
Local Distribution Frame (I/LDF) Condition	1- Good
Deficiency	No deficiencies recorded
	Inspected
Main Equipment Rack (MDF) Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected 3- Fair
Condition	
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Boiler Room
Deficiency Quantity	1 FACIL
Quantity Uom Potential Action	EACH DEDLACE LIDERADE
	REPLACE-UPGRADE PRIORITY 1
Urgency of Action Purpose of Action	LEVEL 2
Violations	No violations recorded
Deficiency	PANEL BOARD DOOR LOCK IS MISSING
Deficiency Location/Instance Deficiency Quantity	Boiler Room
• • •	1 FACH
Quantity Uom Potential Action	EACH MAINTENIANCE
	MAINTENANCE
Urgency of Action Purpose of Action	PRIORITY 2 LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type Condition	Inspected 3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Electrical Room
Quantity Uom	I EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
	Inspected
Molded Case Circuit Breaker Type	
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance Deficiency Quantity	Throughout the Building
Deficiency Quantity	14

Building Condition Assessment Survey 2023-2024

Question	Response	
PANEL BOARD		
Molded Case Circuit Breaker Type		
Quantity Uom	EACH	
Potential Action	REPLACE-UPGRADE	
Urgency of Action	PRIORITY 1	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	NO SPARE	
Deficiency Location/Instance	Corridor near Room 261	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	REPLACE PANEL BOARD	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Deficiency	PANEL BOARD DOOR LOCK IS MISSING	
Deficiency Location/Instance	5th Floor Gymnasium	
Deficiency Quantity	1	
Quantity Uom	EACH	
Potential Action	MAINTENANCE	
Urgency of Action	PRIORITY 2	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
PUBLIC ADDRESS SYSTEM	Under construction	
SECURITY	Inspected	
IPDVS/CCTV System	Inspected	
Condition	2- Between Good and Fair	
Installation Year	2015	-
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Intrusion Alarm System	Inspected	
Central Control Panel	Inspected	
Instance	Room 101	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Model	Vista 128BPT	
Installation Year	2014	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Inspected	
Remote Annunciator		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
Lighting - Security	Inspected	
Condition	1- Good	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Question		Response
SERVICE	SWITCH	Inspected
	Instance	Electrical Room
	Instance Condition	2- Between Good and Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	Main Switch
	Capacity/Size Quantity	2000
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Nameplate
	Installation Year	2007
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
	Instance	Electrical Room
	Instance Condition	3- Fair
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	Temporary Building Fused 350 Amps
	Capacity/Size Quantity	350
	Capacity/Size UOM	Amps
	Source of Capacity/Size	Fuse Size
	Installation Year	1969
	Source of Installation Year	Documented
	Deficiency	BEYOND USEFUL LIFE
	Deficiency Location/Instance	Electrical Room
	Deficiency Quantity	1
	Quantity Uom	EACH
	Potential Action	REPLACE
	Urgency of Action	PRIORITY 1
	Purpose of Action	LEVEL 2
	Violations	No violations recorded
CWITCHI		Inspected
SWITCHI		3
Number	-	Inspected
	sconnect Switch Type	Electrical Room
	Instance	2- Between Good and Fair
	Instance Condition	
	Instance Quantity	1
	Instance Quantity Uom	EACH
	Manufacturer	Square D
	EquipmentId	N/A
	Capacity/Size Quantity	2000
	Capacity/Size UOM	Amps Total
	Capacity/Size 2 Quantity	2
	Capacity/Size 2 UOM	Section(s)
	Source of Capacity/Size	Nameplate
	Installation Year	2007
	Source of Installation Year	Documented
	Deficiency	No deficiencies recorded
Fused K	nife Switch Type	Does not exist
Molded	Case Circuit Breaker Type	Does not exist
TELEPHO	ONE SYSTEM	Inspected
PBX/Inte		Inspected
Conditi		3- Fair
	Deficiency	No deficiencies recorded
Standard	•	Inspected
Stanuare	1	поросни

Building Condition Assessment Survey 2023-2024

Question	Response	
TELEPHONE SYSTEM		_
Standard		
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	