Building Condition Assessment Survey 2023-2024

Electrical Inspection M453

| Asset: | PRE-K CENTER @ 2 LAFAYETTE STREET - MANHATTAN, 2 LAFAYETTE STREET, MANHATTAN, NY, |
|--------|---|
| | 10007 |

| Inspection Id | Inspection Type | Time In | Last Edited |
|---------------|-----------------|--------------------|--------------------|
| 3753 | ELECTRICAL | 2024-03-07 11:35AM | 2024-03-28 10:53AM |

Asset Data

| issei Duiu | |
|---|--|
| Question | Answer |
| Have any Systems/Major Building Components been upgraded? | Systems: All Other Electrical Systems and Components |
| | Years: 2015 |
| | Systems: Service Switch |
| | Years: 1990 |
| Type of Service | Below Ground |
| Does Interactive Whiteboard (IWB) Exist? | Yes |
| Water Penetration In Electrical Room? | No |

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

| Question | Response |
|--|----------|
| Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in | No |
| your building? | |

Priority Condition

| Exist | Priority | Condition | Component | Location | Person(s) | Person(s) | Photo |
|------------|----------------------------------|---|----------------------|------------------------|------------|-----------|-------|
| Last Year? | Category | Description | Affected | Description | Notified | Title | Image |
| No | Fire Alarm System - Defective | Supervisory fault shown on the panel's screen | Fire Alarm System | Main Entrance Lobby | Jose Velez | Handyman | |

Inspection

| Question | Response | |
|---|--------------------------|--|
| llectrical | | |
| ATHLETIC FIELD | Does not exist | |
| AUDITORIUM | Does not exist | |
| CAFETERIA | Does not exist | |
| CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE | Inspected | |
| Lighting | Inspected | |
| Does a Chandelier Exist? | No | |
| Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - LED | Does not exist | |
| COMPUTER LAB | Does not exist | |
| GYMNASIUM | Does not exist | |
| KITCHEN | Does not exist | |
| LIBRARY | Does not exist | |
| LOCKER ROOM | Does not exist | |

Building Condition Assessment Survey 2023-2024

| tem inspection | | 1,110 |
|--|--|-------|
| Question | Response | |
| MULTIPURPOSE ROOM | Inspected | |
| Instance on Room 109 | Inspected | |
| Lighting | | |
| Instance on Room 109 | Inspected | |
| Lighting Fixture - Fluorescent | | |
| Instance on Room 109 | Inspected | |
| Pendant Mounted | | |
| Instance on Room 109 | Inspected | |
| Instance Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Surface Mounted | | |
| Instance on Room 109 | Does not exist | |
| Recessed Mounted | | |
| Instance on Room 109 | Does not exist | |
| Lighting Fixture - HID | | |
| Instance on Room 109 | Does not exist | |
| Lighting Fixture - Incandescent | | |
| Instance on Room 109 | Does not exist | |
| Lighting Fixture - LED | | |
| Instance on Room 109 | Does not exist | |
| Local Sound System | | |
| Instance on Room 109 | Does not exist | |
| Projection System | | |
| Instance on Room 109 | Does not exist | |
| Theater Lighting System | | |
| Instance on Room 109 | Does not exist | |
| SCIENCE DEMO ROOM | Does not exist | |
| SCIENCE LAB | Does not exist | |
| SCIENCE PREP ROOM | Does not exist | |
| SWIMMING POOL | Does not exist | |
| TOILET ROOM - STAFF | Inspected | |
| | Inspected | |
| Lighting Lighting Fixture - Fluorescent | Inspected | |
| Pendant Mounted | Does not exist | |
| Surface Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Recessed Mounted | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Lighting Fixture - HID | Does not exist | |
| Lighting Fixture - Incandescent | Does not exist | |
| Lighting Fixture - Incandescent Lighting Fixture - LED | Does not exist | |
| | | |
| TOILET ROOM - STUDENT | Inspected | |
| Lighting | Inspected Inspected | |
| Lighting Fixture - Fluorescent Pendant Mounted | Does not exist | |
| Surface Mounted | Does not exist Does not exist | |
| | Inspected | |
| Recessed Mounted Condition | 2- Between Good and Fair | |
| | No deficiencies recorded | |
| Deficiency Lighting Fixture - HID | No deficiencies recorded Does not exist | |
| | Lines not exist | |

Building Condition Assessment Survey 2023-2024

| cirical inspection | | W1433 |
|------------------------------------|--------------------------|-------|
| Question | Response | |
| TOILET ROOM - STUDENT | | |
| Lighting | | |
| Lighting Fixture - LED | Does not exist | |
| AUXILIARY SIGNAL/BELL SYSTEM | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| EMERGENCY DC STANDBY BATTERY POWER | Does not exist | |
| | Does not exist | |
| EMERGENCY GENERATOR SET | | |
| EMERGENCY LIGHT/EXIT LIGHT PANEL | Does not exist | |
| EMERGENCY LIGHTING | Inspected | |
| Battery Pack | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Non Battery Pack | Does not exist | |
| EXIT LIGHT | Inspected | |
| Battery Pack | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Non Battery Pack | Does not exist | |
| EXIT/EMERGENCY LIGHT | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| FIRE ALARM SYSTEM | Inspected | |
| Bell/Horn | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Strobe | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Manual Pull Station | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Fan Shutdown Control | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Duct Smoke Detector | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Area Smoke Detector | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| CO Detector | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Heat Detector | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Elevator Recall | Does not exist | |
| Magnetic Door Holder/Contactor | Does not exist | |
| Fused Cutout Panel | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Fire Alarm Digital Communicator | Does not exist | |
| Main Panel | Inspected | |

Building Condition Assessment Survey 2023-2024

| nestion | Response |
|--|---------------------------------------|
| | жэронос |
| FIRE ALARM SYSTEM | |
| Main Panel Bell At Panel | Does not exist |
| | Inspected |
| Fire Alarm Control Panel (Electronic) Instance | Main Entrance Lobby |
| Instance Condition | 3- Fair |
| | |
| Instance Quantity | 1 EACH |
| Instance Quantity Uom | |
| Manufacturer Model | Mircom FX - 2000 |
| | FX - 2000 Fire Alarm Control Panel |
| EquipmentId Installation Year | 2015 |
| Source of Installation Year | Documented |
| Deficiency | SYSTEM DEFECTIVE |
| Deficiency Quantity | 1 |
| Quantity Uom | EACH |
| Potential Action | REPAIR SYSTEM |
| Urgency of Action | PRIORITY 5 |
| Purpose of Action | LEVEL 6 |
| Violations | No violations recorded |
| Fire Alarm Control Panel (Standard) | Does not exist |
| Sub-Panel | Does not exist |
| Remote Annunciator | Inspected |
| Display Monitor | Does not exist |
| Panel | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Printer | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Punch Register | Does not exist |
| Sprinkler Flow/Air Pressure Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Tamper Flow Switch/Chain | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| GROUNDING SYSTEM | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| | Does not exist |
| NTERCOM SYSTEM | |
| LAN | Inspected |
| Local Distribution Frame (I/LDF) | Does not exist |
| Main Equipment Rack (MDF) | Inspected 2- Between Good and Fair |
| Condition | |
| Deficiency | No deficiencies recorded |
| LIGHTNING PROTECTION | Does not exist |
| MOTOR CONTROLLER | Does not exist |
| PANEL BOARD | Inspected |
| Fused Disconnect Switch Type | Does not exist |
| Fused Knife Switch Type | Does not exist |
| Fused Toggle Switch Type | Does not exist |
| Molded Case Circuit Breaker Type | Inspected |

Building Condition Assessment Survey 2023-2024

| ical Inspection | M4 |
|----------------------------------|--|
| uestion | Response |
| PANEL BOARD | |
| Molded Case Circuit Breaker Type | |
| Deficiency | No deficiencies recorded |
| PUBLIC ADDRESS SYSTEM | Inspected |
| Instance | MDF Room C03 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Bogen Multicom - 2000 |
| Installation Year | 2015 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| SECURITY | Inspected |
| IPDVS/CCTV System | Inspected |
| Condition | 2- Between Good and Fair |
| Installation Year | 2015 |
| Source of Installation Year | Documented |
| Deficiency | CAMERA NOT OPERATIONAL |
| Deficiency Location/Instance | Exterior Wall by Main Entrance, 1st Floor Corridor |
| Deficiency Quantity | 2 |
| Quantity Uom | EACH |
| Potential Action | REPLACE |
| Urgency of Action | PRIORITY 4 |
| Purpose of Action | LEVEL 3 |
| Violations | No violations recorded |
| Intrusion Alarm System | Inspected |
| Central Control Panel | Inspected |
| Instance | MDF Room C03 |
| Instance Condition | 2- Between Good and Fair |
| Instance Quantity | 1 |
| Instance Quantity Uom | EACH |
| Model | Vista 128BPT |
| Installation Year | 2015 |
| Source of Installation Year | Documented |
| Deficiency | No deficiencies recorded |
| Infrared Sensor | Inspected |
| Condition | 2- Between Good and Fair |
| | |
| Deficiency | No deficiencies recorded |
| Panic Switch | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Remote Annunciator | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Siren/Strobe | Inspected |
| Condition | 2- Between Good and Fair |
| Deficiency | No deficiencies recorded |
| Lighting - Security | Inaccessible |
| SERVICE SWITCH | Inspected |
| Instance | Main Building - Electrical Room |
| Instance Condition | 3- Fair |
| | |
| Instance Quantity | 1 FACH |
| Instance Quantity Uom | EACH |

Building Condition Assessment Survey 2023-2024

| Question | Response | |
|-----------------------------|--------------------------|--|
| SERVICE SWITCH | | |
| EquipmentId | PERK 453 | |
| Capacity/Size Quantity | 400 | |
| Capacity/Size UOM | Amps | |
| Source of Capacity/Size | Nameplate | |
| Installation Year | 1990 | |
| Source of Installation Year | Documented | |
| Deficiency | No deficiencies recorded | |
| SWITCHBOARD | Does not exist | |
| TELEPHONE SYSTEM | Inspected | |
| PBX/Intercom | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| Standard | Inspected | |
| Condition | 2- Between Good and Fair | |
| Deficiency | No deficiencies recorded | |
| TRANSFORMER | Does not exist | |