Asset:	JEROME PAR	K EDUCATIONAL BUII	LDING, 2865 CLAI	FLIN AVENUE,	BRONX, NY	, 10468	
Inspectio	n Id Inspection Type				Time	In	Last Edited
	1153 ELECTRICAL				2023-	-11-21 10:21A	M 2024-01-25 12:53PN
sset Data							
Question				Answer			
Have any	Systems/Major Building	Components been upgraded?		Systems:	All Electrical	Systems and C	omponents
				Years:	2017		
Type of S	Service			Below Gr	ound		
Does Inte	eractive Whiteboard (IWB	B) Exist?		Yes			
	netration In Electrical Ro			No			
		IN FIRE RESCUE AREA	AS		<u> </u>		
Question Are the		tance Areas, Fire Rescue Area	s, and/or Holding Roo		Response No		
your bu	ilding?	<u> </u>					
<i>Priority Co</i> Exist		Condition	C	T4'	D(-)	D(-)	Dl4-
Exist Last Year?	Priority Category	Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
No	Intercom - Not	Not Operational	Intercom	Elevator	Donnie	Handyman	No Photo Taken
NO	Operational	Not Operational	System - Elevator	Device ID - 2P3986	Barranco	Handyman	100 Thoto Taken
Inspection	1						
Question	ı			Response	:		
Electrica	ıl						
ATHL	ETIC FIELD			Does not	exist		
AUDIT	TORIUM			Does not exist			
CAFE	ΓERIA			Inspected			
	Instance on Basemen	t		Inspected			
Light	ting						
	Instance on Basemen	t		Inspected			
Lig	hting Fixture - Fluoresc	ent					
_	Instance on Basemen	t		Inspected			
P	endant Mounted						
_	Instance on Basemen	t		Does not	exist		
S	urface Mounted						
_	Instance on Basemen	t		Does not	exist		
R	ecessed Mounted						
	Instance on Basemen	t		Inspected		•	
	Instance Condition				en Good and Fa		
	Deficiency			No defici	encies recorded		
Lig	hting Fixture - HID Instance on Basemen			D	:-4		
		-		Does not	exist		
Lig	Instance on Basemen			Does not	evict		
		<u> </u>		Does not	CAISt		
Lig	hting Fixture - LED Instance on Basemen	f		Inspected			
P	endant Mounted	•		търески			
•	Instance on Basemen	t		Does not	exist		
$\overline{\mathbf{S}}$	urface Mounted						
~	Instance on Basemen	t		Does not	exist		
R	ecessed Mounted						
	Instance on Basemen	t		Inspected			
	Instance Condition			2- Betwee	en Good and Fa	ir	
	Deficiency			LIGHTIN	IG FIXTURE N	OT OPERATION	DNAL
	Deficiency Quantit	ry .		1			

Electrical Inspection	X//:	9
Question	Response	

· · · · · · · · · · · · · · · · · · ·		
Question	Response	
CAFETERIA		
Lighting		
Lighting Fixture - LED		
Recessed Mounted		
Quantity Uom	EACH	
Potential Action	REPLACE	
Urgency of Action	PRIORITY 3	
Purpose of Action	LEVEL 2	
Violations	No violations recorded	
Local Sound System		
Instance on Basement	Inspected	
Instance Condition	2- Between Good and Fair	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Projection System		
Instance on Basement	Does not exist	
Theater Lighting System		
Instance on Basement	Does not exist	
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected	
Lighting	Inspected	
Does a Chandelier Exist?	No	
Lighting Fixture - Fluorescent	Inspected	
Pendant Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Inspected	
Pendant Mounted	Does not exist	
Surface Mounted	Does not exist	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
	Does not exist	
COMPUTER LAB		
GYMNASIUM	Does not exist	
KITCHEN	Inspected	
Instance on Basement	Inspected	
Lighting		
Instance on Basement	Inspected	
Lighting Fixture - Fluorescent		
Instance on Basement	Inspected	
Pendant Mounted		
Instance on Basement	Does not exist	
Surface Mounted		
Instance on Basement	Does not exist	
Recessed Mounted		
Instance on Basement	Inspected	

Electrical Inspection	X779

······································		
Question	Response	
KITCHEN		
Lighting		
Lighting Fixture - Fluorescent		
Recessed Mounted		
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID		
Instance on Basement	Does not exist	
Lighting Fixture - Incandescent		
Instance on Basement	Does not exist	
Lighting Fixture - LED		
Instance on Basement	Does not exist	
LIBRARY	Inspected	
Instance on Room 201	Inspected	
Lighting	ı	
Instance on Room 201	Inspected	
Lighting Fixture - Fluorescent	-	
Instance on Room 201	Inspected	
Pendant Mounted	<u> </u>	
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on Room 201	Does not exist	
Recessed Mounted		
Instance on Room 201	Does not exist	
Lighting Fixture - HID	2000 1000 01100	
Instance on Room 201	Does not exist	
Lighting Fixture - Incandescent	2000 1000 0000	
Instance on Room 201	Does not exist	
Lighting Fixture - LED	Does not exist	
Instance on Room 201	Does not exist	
Raceway With Receptacles	Does not exist	
Instance on Room 201	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Projection System	No deficiences recorded	
Instance on Room 201	Does not exist	
LOCKER ROOM	Does not exist	
MULTIPURPOSE ROOM	Inspected	
Instance on 1st Floor	Inspected	
Lighting		
Instance on 1st Floor	Inspected	
Lighting Fixture - Fluorescent		
Instance on 1st Floor	Inspected	
Pendant Mounted	Y •	
Instance on 1st Floor	Inspected	
Instance Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Surface Mounted		
Instance on 1st Floor	Does not exist	
Recessed Mounted		
Instance on 1st Floor	Does not exist	

Building Condition Assessment Survey 2023-2024

Question	Response
MULTIPURPOSE ROOM	- Pro-
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	2000 100 01100
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	Does not exist
Instance on 1st Floor	Inspected
Pendant Mounted	nispected
Instance on 1st Floor	Does not exist
Surface Mounted	DOCS HOL CAISE
	Inomostod
Instance on 1st Floor	Inspected 2- Between Good and Fair
Instance Condition	
Deficiency	No deficiencies recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Local Sound System	T
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Projection System	T 1
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System Instance on 1st Floor	Turn out od
	Inspected
Dimming System	
Instance on 1st Floor	Inspected
Instance Condition	4- Between Fair and Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1 FACIL
Quantity Uom Potential Action	EACH
Urgency of Action	REPAIR PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
	No violations recorded
Theater Lighting	Incorporad
Instance on 1st Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded Does not exist

SCIENCE LAB

Lighting

Instance on Room 301

Instance on Room 301

Instance on Room 301

Power Panel?

Alternative Use

Lighting Fixture - Fluorescent
Instance on Room 301

Pendant Mounted

Inspected

Inspected

Inspected

Inspected

Inspected

No

Yes

Building Condition Assessment Survey 2023-2024

Response	
2- Between Good and Fair	
No deficiencies recorded	
Does not exist	
Does not exist	
200 100 01110	
Does not exist	
200 100 01110	
Inspected	
- Inspection	
Inspected	
2- Between Good and Fair	
Two deficiences recorded	
Does not exist	
Does not exist	
Does not exist	
DOGS HOT CAIST	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
Does not exist	
_	
mspecteu	
	Does not exist Does not exist Does not exist Does not exist Inspected Inspected 2- Between Good and Fair No deficiencies recorded Does not exist Does not exist

No deficiencies recorded

Inspected

Deficiency

Surface Mounted

Building Condition Assessment Survey 2023-2024

Electrical Inspection X779

icai Inspection		A 11
nestion	Response	
FOILET ROOM - STUDENT		
Lighting		
Lighting Fixture - Fluorescent		
Surface Mounted		
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Recessed Mounted	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Lighting Fixture - HID	Does not exist	
Lighting Fixture - Incandescent	Does not exist	
Lighting Fixture - LED	Does not exist	
AUXILIARY SIGNAL/BELL SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
EMERGENCY DC STANDBY BATTERY POWER	Does not exist	
EMERGENCY GENERATOR SET	Does not exist	
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist	
EMERGENCY LIGHTING	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT LIGHT	Inspected	
Battery Pack	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Non Battery Pack	Does not exist	
EXIT/EMERGENCY LIGHT	Does not exist	
FIRE ALARM SYSTEM	Inspected	
Bell/Horn	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Strobe	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Manual Pull Station	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fan Shutdown Control	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Duct Smoke Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Area Smoke Detector	Inspected	<u> </u>
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
CO Detector	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Heat Detector	Inspected	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X779

•		
nestion	Response	
FIRE ALARM SYSTEM		
Heat Detector		
Deficiency	No deficiencies recorded	
Elevator Recall	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Magnetic Door Holder/Contactor	Does not exist	
Fused Cutout Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Fire Alarm Digital Communicator	Does not exist	
Main Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Main Entrance Lobby	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Mircom	
Model	FX - 2000	
EquipmentId	Fire Alarm Control Panel	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Sub-Panel Sub-Panel	Inspected	
Bell At Panel	Does not exist	
Fire Alarm Control Panel (Electronic)	Inspected	
Instance	Boiler Room	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Edwards	
Model	E-FSC	
EquipmentId	N/A	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fire Alarm Control Panel (Standard)	Does not exist	
Remote Annunciator	Inspected	
Display Monitor	Does not exist	
Panel	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Printer	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Punch Register	Does not exist	
Sprinkler Flow/Air Pressure Switch	Does not exist	
Tamper Flow Switch/Chain	Does not exist	
GROUNDING SYSTEM	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	

Building Condition Assessment Survey 2023-2024

Electrical Inspection X779

Question	Response
INTERCOM SYSTEM	
Elevator	Inspected
Condition	4- Between Fair and Poor
Deficiency	INTERCOM CABINET NOT OPERATIONAL
Deficiency Location/Instance	Elevator Device ID - 2P3986
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Does not exist
Main Equipment Rack (MDF)	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROL CENTER	Does not exist
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Telecom Room 306B
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Bogen HTA250A
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Inspected
Condition	2- Between Good and Fair
Installation Year	2017
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Custodian's Office - Room B04
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
mounte Quantity Com	Vista 128BPT
Model	VISIA 120DF I
Model Installation Year	2017

Question	Response	
SECURITY		
Intrusion Alarm System		
Central Control Panel		
Deficiency	No deficiencies recorded	
Infrared Sensor	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Panic Switch	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Remote Annunciator	Inspected	
Condition	2- Between Good and Fair	
Deficiency	No deficiencies recorded	
Siren/Strobe	Inspected	
Condition	2- Between Good and Fair	
	No deficiencies recorded	
Deficiency		
Lighting - Security Condition	Inspected 2- Between Good and Fair	
Deficiency	No deficiencies recorded	
SERVICE SWITCH	Inspected	
Instance	Electrical Room B06	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	SSW#1	
Capacity/Size Quantity	2000	
Capacity/Size UOM Source of Capacity/Size	Amps Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
SWITCHBOARD	Inspected	
Number of Spares	10	
Fused Disconnect Switch Type	Inspected	
Instance	Electrical Room B06	
Instance Condition	2- Between Good and Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Manufacturer	Square D	
EquipmentId	MDB Section 1, MDB Section 2	
Capacity/Size Quantity	2000	
Capacity/Size UOM	Amps Total	
Capacity/Size 2 Quantity	2	
Capacity/Size 2 UOM	Section(s)	
Source of Capacity/Size	Nameplate	
Installation Year	2017	
Source of Installation Year	Documented	
Deficiency	No deficiencies recorded	
Fused Knife Switch Type	Does not exist	
Molded Case Circuit Breaker Type	Does not exist	
TELEPHONE SYSTEM	Inspected	
PBX/Intercom	Inspected	
Condition	2- Between Good and Fair	

Building Condition Assessment Survey 2023-2024

ctrical Inspection		X779	
Question	Response		
TELEPHONE SYSTEM			
Standard	Inspected		
Condition	2- Between Good and Fair		
Deficiency	No deficiencies recorded		

Does not exist

TRANSFORMER