#### **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

	P.S. 53 MINISC	HOOL #2 - BRONX, 360 E	AST 168 STREE	Γ, BRONX, NY,	10456		
Inspectio	n Id Inspection Type				Time	In	Last Edited
	2089 ELECTRICAL				2024-	01-03 08:34AN	M 2024-01-30 08:57A
sset Data							
Question	l			Answer			
Have any Systems/Major Building Components been upgraded?				Systems:	Exit Lights (E	Battery Pack)	
				Years:	2019		
				Systems:	Emergency L	ighting (Battery	Pack)
				Years:	2018		
				Systems:	Partial Molded Case Circuit Breaker Panel Boards 2016 LAN, Telephone and Public Address Systems		
				Years:			
				Systems:			
				Years:	2011		
				Systems:	Fire Alarm Sy	vstem	
				Years:	2010		
				Systems:		ts, Intrusion Ala	rm System
				Years:	1997		
Type of S				Below Gro	und		
	eractive Whiteboard (IWB)			Yes			
	netration In Electrical Room			No			
		N FIRE RESCUE AREAS					
Question		4 E' D 4	1/ II 11: D		esponse		
	ilding?	ince Areas, Fire Rescue Areas, a	nd/or Holding Room	ns in N	0		
vour bi							
-							
riority Co	ondition	Condition	Component	Location	Person(s)	Person(s)	Photo
-	ondition Priority	Condition Description	<b>Component</b> Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
riority Co Exist Last Year?	Priority Category	Description	Affected	Description	Notified	Title	
riority Co Exist	ondition Priority		-		. ,		
riority Co Exist Last Year?	Priority Category Fire Alarm System -	Description Mother aboard for Fire	Affected Fire Alarm	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year?	Priority Category Fire Alarm System - Components Not	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year?	Priority Category Fire Alarm System - Components Not	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year?	Priority Category Fire Alarm System - Components Not	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year?	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year? No	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year? No	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby	<b>Notified</b> Vladimir	Title	
riority Co Exist Last Year? No <i>inspection</i> Question Electrica	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby	Notified Vladimir Pali	Title	
riority Co Exist Last Year? No <i>inspection</i> Question Electrica ATHL	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby Response	Notified Vladimir Pali	Title	
riority Co Exist Last Year? No Uuestion Electrica ATHLI AUDIT	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby Response Does not e	Notified Vladimir Pali	Title	
riority Co Exist Last Year? No No Question Electrica ATHLI AUDIT	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby Response Does not e Does not e	Notified Vladimir Pali	Title	
riority Co Exist Last Year? No No Question Electrica ATHLI AUDIT	Priority Category Fire Alarm System - Components Not Operational	Description           Mother aboard for Fire           Alarm Panel is out of	Affected Fire Alarm System - Main	Description Main Entrance Lobby Response Does not e Inspected	Notified Vladimir Pali	Title	

Ig Instance on 1st Floor Inspected Pendant Mounted Instance on 1st Floor Does not exist **Surface Mounted** Instance on 1st Floor Inspected 3- Fair Instance Condition Deficiency LIGHTING FIXTURE BEYOND USEFUL LIFE Deficiency Quantity 36 Quantity Uom EACH Potential Action REPLACE-UPGRADE Urgency of Action PRIORITY 1

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

	Λδ
Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
Local Sound System	
Instance on 1st Floor	Inspected
Instance Condition	5- Poor
Installation Year	1997
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor	Does not exist
Theater Lighting System	
Instance on 1st Floor	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	Inspected
Lighting	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	215
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Does not exist
KITCHEN	Inspected
Instance on 1st Floor	Inspected
Lighting Instance on 1st Floor	Inspected
	IIIspecieu
Lighting Fixture - Fluorescent	

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

ncui Inspection	АО
uestion	Response
KITCHEN	
Lighting	
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action Purpose of Action	PRIORITY 1 LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Does not exist
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent Instance on 1st Floor	Does not exist
	Does not exist
Lighting Fixture - LED Instance on 1st Floor	Does not exist
LIBRARY	Does not exist
LOCKER ROOM	Does not exist
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	2
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	3- Fair

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

uestion	Response
TOILET ROOM - STUDENT	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	6
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Does not exist
EMERGENCY DC STANDBY BATTERY POWER	Does not exist
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Does not exist
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT LIGHT	Inspected
Battery Pack	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Non Battery Pack	Does not exist
EXIT/EMERGENCY LIGHT	Does not exist
FIRE ALARM SYSTEM	Inspected
Bell/Horn	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	Does not exist
Heat Detector	Does not exist
Elevator Recall	Does not exist
Magnetic Door Holder/Contactor	Does not exist
Fused Cutout Panel	Inspected

### **Building Condition Assessment Survey 2023-2024**

#### Electrical Inspection

	Λα
uestion	Response
FIRE ALARM SYSTEM	
Fused Cutout Panel	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	Does not exist
Main Panel	Inspected
Bell At Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	Inspected
Instance	Main Entrance Lobby
Instance Condition	4- Between Fair and Poor
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Manulacturer Model	EST 2
EquipmentId	Fire Alarm Control Panel Mini Building 2
Installation Year	2010
Source of Installation Year	Documented
Deficiency	PANEL NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPAIR
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Fire Alarm Control Panel (Standard)	Does not exist
Sub-Panel	Does not exist
Remote Annunciator	Inspected
Display Monitor	Does not exist
Panel	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
	Does not exist
Printer	
Punch Register	Does not exist
Sprinkler Flow/Air Pressure Switch	Does not exist Does not exist
Tamper Flow Switch/Chain	
GROUNDING SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	Does not exist
LAN	Inspected
Local Distribution Frame (I/LDF)	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	Does not exist
LIGHTNING PROTECTION	Does not exist
MOTOR CONTROLLER	Inspected
MOTOR CONTROLLER MOTOR CONTROL CENTER	Does not exist
MOTOR CONTROL CENTER MOTOR STARTER/CONTACTOR	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Does not exist

# **Building Condition Assessment Survey 2023-2024**

#### **Electrical Inspection**

rical Inspection	Χ
Question	Response
PANEL BOARD	
Fused Disconnect Switch Type	Does not exist
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Does not exist
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Connected to Main Asset X053
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	N/A
Installation Year	2011
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
SECURITY	Inspected
IPDVS/CCTV System	Does not exist
Intrusion Alarm System	Inspected
Central Control Panel	Inspected
Instance	Room 41
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1997
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 41
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	Does not exist
Remote Annunciator	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	Does not exist
SWITCHBOARD	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition Deficiency	3- Fair No deficiencies recorded

# NYC Department of Education Building Condition Assessment Survey 2023-2024

# Electrical Inspection

Question	Response	
TELEPHONE SYSTEM		
Standard	Inspected	
Condition	3- Fair	
Deficiency	No deficiencies recorded	
TRANSFORMER	Does not exist	