

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Asset: TERENCE D. TOLBERT EDUCATION COMPLEX - MANHATTAN, 625 WEST 133 STREET, MANHATTAN, NY, 10027

Inspection Id	Inspection Type	Time In	Last Edited
2271	ELECTRICAL	2024-01-09 08:57AM	2024-01-10 12:32PM

Asset Data

Question	Answer
Have any Systems/Major Building Components been upgraded?	Systems: LAN Years: 2023 Systems: Partial Molded Case Circuit Breaker Panel Board Years: 2022, 2017, 2012, 2000, 1995 Systems: Intercom System (Holding Area) Years: 2020 Systems: Most Security Lights Years: 2019, 2007 Systems: LED Lighting (Boys Locker Room, Gymnasium), Auditorium (Projection System) Years: 2019 Systems: Fire Alarm System (Sprinkler Flow Switch) Years: 2018 Systems: Toilet Rooms Years: 2017, 2013 Systems: Partial Fused Disconnect Switch Type Panel Board Years: 2017, 2011 Systems: Exit/Emergency Lights, Partial Motor Starters, Variable Frequency Drive Years: 2017 Systems: Fire Alarm System (Digital Communicator), Auditorium (House Lighting Except Surface Fluorescent Lighting, Theater Lighting), Public Address System (Amplifier) Years: 2013 Systems: Science Lab - Rooms 147, 149, 247, 249 (Except Lighting) Years: 2012 Systems: Intercom System (Elevator), IPDVS/CCTV System Years: 2010 Systems: Emergency Light/Exit Light Panel, Fire Alarm System Years: 2009 Systems: Interior Fluorescent Lighting, Intrusion Alarm System Years: 1996 Below Ground
Type of Service	Below Ground
Does Interactive Whiteboard (IWB) Exist?	Yes
Water Penetration In Electrical Room?	No

DEDICATED INTERCOMS IN FIRE RESCUE AREAS

Question	Response
Are there any Life Rescue Assistance Areas, Fire Rescue Areas, and/or Holding Rooms in your building?	No

Priority Condition

Exist Last Year?	Priority Category	Condition Description	Component Affected	Location Description	Person(s) Notified	Person(s) Title	Photo Image
Yes	Emergency DC Standby Battery Power - Battery Bank Not Operational	Batteries Bulging and Cracked.	Emergency DC Standby Battery Power	Electrical Room B4	Henry Rosa	Fireman	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Yes	Fire Alarm System - Components Not Operational	N/A	Fire Alarm System - Sprinkler Flow/Air Pressure Switch	Room B2	Henry Rosa	Fireman	
No	Intercom - Not Connected to Remote Monitoring Station	N/A	Intercom System - Elevator	Elevator Device ID: 1P30545	Henry Rosa	Fireman	No Photo Taken

Inspection

Question	Response
Electrical	
ATHLETIC FIELD	Does not exist
AUDITORIUM	Inspected
Instance on 2nd Floor	Inspected
House Lighting	
Instance on 2nd Floor	Inspected
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	7
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1975
Source of Installation Year	Documented

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
AUDITORIUM	
Local Sound System	
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Inspected
Instance Condition	1- Good
Is the projector on a cart or installed on the ceiling?	Ceiling
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Inspected
Dimming System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Deficiency	DIMMING RACK/LIGHT CONSOLE NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 3
Purpose of Action	LEVEL 2
Violations	No violations recorded
Theater Lighting	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
CAFETERIA	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor - Staff	Inspected
Instance on 1st Floor - Students	Inspected
Pendant Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Surface Mounted	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Recessed Mounted	
Instance on 1st Floor - Staff	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	15
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
CAFETERIA	
Lighting	
Lighting Fixture - Fluorescent	
Recessed Mounted	
Instance on 1st Floor - Students	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	155
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Local Sound System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Inspected
Instance Condition	5- Poor
Installation Year	1975
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
Theater Lighting System	
Instance on 1st Floor - Staff	Does not exist
Instance on 1st Floor - Students	Does not exist
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Inspected	Inspected
Lighting	
Does a Chandelier Exist?	No
Lighting Fixture - Fluorescent	
Pendant Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1,000
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Inspected	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
CLASSROOM/CORRIDOR/ADMINISTRATIVE SPACE	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	750
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	Inspected
Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	650
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
COMPUTER LAB	Does not exist
GYMNASIUM	Inspected
Instance on 2nd Floor	Inspected
Lighting	
Instance on 2nd Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Does not exist
Surface Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	17
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor	Inspected
Pendant Mounted	
Instance on 2nd Floor	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
GYMNASIUM	
Lighting	
Lighting Fixture - LED	
Surface Mounted	
Instance on 2nd Floor	Does not exist
Recessed Mounted	
Instance on 2nd Floor	Does not exist
Local Sound System	
Instance on 2nd Floor	Inspected
Instance Condition	5- Poor
Installation Year	1975
Source of Installation Year	Documented
Deficiency	AMPLIFIER NOT OPERATIONAL
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE SYSTEM
Urgency of Action	PRIORITY 2
Purpose of Action	LEVEL 2
Violations	No violations recorded
Projection System	
Instance on 2nd Floor	Does not exist
Scoreboard	
Instance on 2nd Floor	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Theater Lighting System	
Instance on 2nd Floor	Does not exist
KITCHEN	
Instance on 1st Floor	Inspected
Instance on 1st Floor	Inspected
Lighting	
Instance on 1st Floor	Inspected
Lighting Fixture - Fluorescent	
Instance on 1st Floor	Inspected
Pendant Mounted	
Instance on 1st Floor	Does not exist
Surface Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 1st Floor	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	38
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
KITCHEN	
Lighting	
Lighting Fixture - HID	
Instance on 1st Floor	Does not exist
Lighting Fixture - Incandescent	
Instance on 1st Floor	Does not exist
Lighting Fixture - LED	
Instance on 1st Floor	Does not exist
LIBRARY	
Instance on Room 265	Inspected
Lighting	
Instance on Room 265	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 265	Inspected
Pendant Mounted	
Instance on Room 265	Does not exist
Surface Mounted	
Instance on Room 265	Does not exist
Recessed Mounted	
Instance on Room 265	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	41
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Lighting Fixture - HID	
Instance on Room 265	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 265	Does not exist
Lighting Fixture - LED	
Instance on Room 265	Does not exist
Raceway With Receptacles	
Instance on Room 265	Does not exist
Projection System	
Instance on Room 265	Does not exist
LOCKER ROOM	
Instance on 2nd Floor - Boys	Inspected
Alternative Use	Yes
Instance on 2nd Floor - Girls	Inspected
Alternative Use	Yes
Lighting	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Inspected
Lighting Fixture - Fluorescent	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Inspected
Pendant Mounted	
Instance on 2nd Floor - Girls	Does not exist
Surface Mounted	
Instance on 2nd Floor - Girls	Inspected
Instance Condition	3- Fair

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M195

Question	Response
LOCKER ROOM	
Lighting	
Lighting Fixture - Fluorescent	
Surface Mounted	
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	12
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Recessed Mounted	
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - HID	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - Incandescent	
Instance on 2nd Floor - Boys	Does not exist
Instance on 2nd Floor - Girls	Does not exist
Lighting Fixture - LED	
Instance on 2nd Floor - Boys	Inspected
Instance on 2nd Floor - Girls	Does not exist
Pendant Mounted	
Instance on 2nd Floor - Boys	Does not exist
Surface Mounted	
Instance on 2nd Floor - Boys	Does not exist
Recessed Mounted	
Instance on 2nd Floor - Boys	Inspected
Instance Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
MULTIPURPOSE ROOM	Does not exist
SCIENCE DEMO ROOM	Does not exist
SCIENCE LAB	Inspected
Instance on Room 347	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Room 349	Inspected
Power Panel?	Yes
Alternative Use	Yes
Instance on Rooms 147, 149	Inspected
Power Panel?	Yes
Alternative Use	No
Instance on Rooms 247, 249	Inspected
Power Panel?	Yes
Alternative Use	Yes
Lighting	
Instance on Room 347	Inspected
Instance on Room 349	Inspected
Instance on Rooms 147, 149	Inspected
Instance on Rooms 247, 249	Inspected
Lighting Fixture - Fluorescent	
Instance on Room 347	Inspected
Instance on Room 349	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - Fluorescent	
Instance on Rooms 147, 149	Inspected
Instance on Rooms 247, 249	Inspected
Pendant Mounted	
Instance on Room 347	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Room 349	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	24
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms 147, 149	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance on Rooms 247, 249	Inspected
Instance Condition	3- Fair
Deficiency	LIGHTING FIXTURE BEYOND USEFUL LIFE
Deficiency Quantity	48
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Surface Mounted	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Recessed Mounted	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Lighting Fixture - HID	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M195

Question	Response
SCIENCE LAB	
Lighting	
Lighting Fixture - HID	
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Lighting Fixture - Incandescent	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Lighting Fixture - LED	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Emergency Gas Shut-Off Valve	
Instance on Room 347	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Room 349	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 147, 149	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 247, 249	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Emergency Shut-Off Power	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 247, 249	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Power Supply	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Inspected
Instance on Rooms 247, 249	Inspected
Instructor Unit	
Instance on Rooms 147, 149	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Instance on Rooms 247, 249	Inspected
Instance Condition	3- Fair
Deficiency	No deficiencies recorded
Meter Demonstration Unit	
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Student Unit	

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
SCIENCE LAB	
Power Supply	
Student Unit	
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
Projection System	
Instance on Room 347	Does not exist
Instance on Room 349	Does not exist
Instance on Rooms 147, 149	Does not exist
Instance on Rooms 247, 249	Does not exist
SCIENCE PREP ROOM	Does not exist
SWIMMING POOL	Does not exist
TOILET ROOM - STAFF	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
TOILET ROOM - STUDENT	Inspected
Lighting	Inspected
Lighting Fixture - Fluorescent	Inspected
Pendant Mounted	Does not exist
Surface Mounted	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Recessed Mounted	Does not exist
Lighting Fixture - HID	Does not exist
Lighting Fixture - Incandescent	Does not exist
Lighting Fixture - LED	Does not exist
AUXILIARY SIGNAL/BELL SYSTEM	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
EMERGENCY DC STANDBY BATTERY POWER	Inspected
Condition	5- Poor
Deficiency	BATTERY BANK NOT OPERATIONAL
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
EMERGENCY GENERATOR SET	Does not exist
EMERGENCY LIGHT/EXIT LIGHT PANEL	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
EMERGENCY LIGHTING	Inspected
Battery Pack	Inspected

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M195

Question	Response
EMERGENCY LIGHTING	
Battery Pack	
Condition	3- Fair
Deficiency	BATTERY NOT OPERATIONAL
Deficiency Location/Instance	Corridor near Custodian's Office, Auditorium, Corridor near Room 259, Main Entrance Lobby
Deficiency Quantity	5
Quantity Uom	EACH
Potential Action	REPLACE BATTERY
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35655395Z
Non Battery Pack	
Condition	Inspected
Deficiency	No deficiencies recorded
EXIT LIGHT	
Battery Pack	
Condition	Inspected
Deficiency	3- Fair
Deficiency	FIXTURE LAMP NOT OPERATIONAL
Deficiency Location/Instance	Gymnasium
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	MAINTENANCE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 4
Violations	35655395Z
Non Battery Pack	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
EXIT/EMERGENCY LIGHT	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
FIRE ALARM SYSTEM	
Bell/Horn	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Strobe	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Manual Pull Station	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fan Shutdown Control	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Duct Smoke Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Area Smoke Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
CO Detector	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Heat Detector	
Condition	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
FIRE ALARM SYSTEM	
Heat Detector	
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Elevator Recall	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Magnetic Door Holder/Contactor	
	Does not exist
Fused Cutout Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Digital Communicator	
	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	Honeywell
EquipmentId	Central Station Communicator
Installation Year	2013
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Main Panel	
	Inspected
Bell At Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Electronic)	
	Inspected
Instance	Main Entrance Lobby
Instance Condition	2- Between Good and Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	General Electric
Model	EST 2
EquipmentId	Fire Alarm Control Panel
Installation Year	2009
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Fire Alarm Control Panel (Standard)	
	Does not exist
Sub-Panel	
	Does not exist
Remote Annunciator	
	Inspected
Display Monitor	
	Does not exist
Panel	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
Printer	
Condition	Inspected
Deficiency	5- Poor
Deficiency	PRINTER NOT OPERATIONAL
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 2
Violations	No violations recorded
Punch Register	
	Does not exist
Sprinkler Flow/Air Pressure Switch	
	Inspected

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
FIRE ALARM SYSTEM	
Sprinkler Flow/Air Pressure Switch	
Condition	4- Between Fair and Poor
Deficiency	SWITCH NOT OPERATIONAL
Deficiency Location/Instance	Room B2
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	12131008H
Tamper Flow Switch/Chain	
Condition	Inspected
Deficiency	2- Between Good and Fair
Deficiency	No deficiencies recorded
GROUNDING SYSTEM	
Condition	Inspected
Deficiency	3- Fair
Deficiency	No deficiencies recorded
INTERCOM SYSTEM	
Condition	Inspected
Elevator	
Condition	Inspected
Condition	3- Fair
Deficiency	NOT CONNECTED TO REMOTE MONITORING STATION
Deficiency Location/Instance	Elevator Device ID: 1P30545
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	INSTALL CONNECTION
Urgency of Action	PRIORITY 5
Purpose of Action	LEVEL 6
Violations	No violations recorded
Holding Area	
Condition	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LAN	
Condition	Inspected
Local Distribution Frame (L/DF)	
Condition	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
Main Equipment Rack (MDF)	
Condition	Inspected
Condition	1- Good
Deficiency	No deficiencies recorded
LIGHTNING PROTECTION	
Condition	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
MOTOR CONTROLLER	
Condition	Inspected
MOTOR CONTROL CENTER	
Instance	Inspected
Instance	Mechanical Room 378
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E. Imperial Corp
EquipmentId	N/A
Capacity/Size Quantity	200
Capacity/Size UOM	Amps
Capacity/Size 2 Quantity	1
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Inspector Estimate
Installation Year	1975

NYC Department of Education
Building Condition Assessment Survey 2023-2024

Electrical Inspection

M195

Question	Response
MOTOR CONTROLLER	
MOTOR CONTROL CENTER	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 378
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
MOTOR STARTER/CONTACTOR	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
Variable Frequency Drive	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
PANEL BOARD	Inspected
Fused Disconnect Switch Type	Inspected
Condition	2- Between Good and Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Mechanical Room 378
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Fused Toggle Switch Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Molded Case Circuit Breaker Type	Inspected
Condition	3- Fair
Deficiency	PANEL BOARD BEYOND USEFUL LIFE
Deficiency Location/Instance	Throughout the Building
Deficiency Quantity	35
Quantity Uom	EACH
Potential Action	REPLACE-UPGRADE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
PUBLIC ADDRESS SYSTEM	Inspected
Instance	Room 261
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Dukane 250
Installation Year	1975

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
PUBLIC ADDRESS SYSTEM	
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Room 261
Deficiency Quantity	155,000
Quantity Uom	S.F.
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SECURITY	
	Inspected
IPDVS/CCTV System	
	Inspected
Condition	3- Fair
Installation Year	2010
Source of Installation Year	Documented
Deficiency	No deficiencies recorded
Intrusion Alarm System	
	Inspected
Central Control Panel	
	Inspected
Instance	Custodian's Office
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Model	Vista - 50P
Installation Year	1996
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Custodian's Office
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 3
Violations	No violations recorded
Infrared Sensor	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Panic Switch	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Remote Annunciator	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Siren/Strobe	
	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Lighting - Security	
	Inspected
Condition	2- Between Good and Fair
Deficiency	No deficiencies recorded
SERVICE SWITCH	
	Inspected
Instance	Electrical Room B4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
SERVICE SWITCH	
EquipmentId	MDB Main Switch
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	Heating Equipment Service SW.
Capacity/Size Quantity	800
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Instance	Electrical Room B4
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E.
EquipmentId	Air Cond. Service SW.
Capacity/Size Quantity	1200
Capacity/Size UOM	Amps
Source of Capacity/Size	Nameplate
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
SWITCHBOARD	Inspected
Number of Spares	4
Fused Disconnect Switch Type	Inspected
Instance	Electrical Room B4

**NYC Department of Education
Building Condition Assessment Survey 2023-2024**

Electrical Inspection

M195

Question	Response
SWITCHBOARD	
Fused Disconnect Switch Type	
Instance Condition	3- Fair
Instance Quantity	1
Instance Quantity Uom	EACH
Manufacturer	I.T.E. Imperial Corp.
EquipmentId	N/A
Capacity/Size Quantity	4000
Capacity/Size UOM	Amps Total
Capacity/Size 2 Quantity	6
Capacity/Size 2 UOM	Section(s)
Source of Capacity/Size	Service Switch Size
Installation Year	1975
Source of Installation Year	Documented
Deficiency	BEYOND USEFUL LIFE
Deficiency Location/Instance	Electrical Room B4
Deficiency Quantity	1
Quantity Uom	EACH
Potential Action	REPLACE
Urgency of Action	PRIORITY 1
Purpose of Action	LEVEL 2
Violations	No violations recorded
Fused Knife Switch Type	Does not exist
Molded Case Circuit Breaker Type	Does not exist
TELEPHONE SYSTEM	Inspected
PBX/Intercom	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
Standard	Inspected
Condition	3- Fair
Deficiency	No deficiencies recorded
TRANSFORMER	Does not exist