# **Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection		Q822
Asset: P.S. 811 MINISCHOOL (OLD 136 MN)-Q, 114-36 202	ND STREET, New York, 11412	
Inspection Id Inspection Type	Time In	Last Edited
ME: Q822 Mechanical	2023-11-14 9:44 AM	2023-11-20 12:29 PM
Asset Data		
Question	Answer	
Are there fuel tanks?	No	
Total # of water main service entries to the asset  MERs/Fan Rooms Locations	1 MER M-8	
Are there any spaces with Missing or Defective CO Detectors?	No No	
Are there any Emergency Stop Switches with Missing Hammers?	No	
Are there any Painted/Obstructed Sprinkler Heads?	No	
Have any Systems/Major Building Components been upgraded?	No	
Priority Condition		
Priority Priority Condition Component Location Condition Exist Category Description Affected Description Last Year?	Person(s) Person(s) Title Status Notified	PhotoImage
No condition recorded		
Inspection		
Question	Response	
Mechanical		
AIR CONDITIONING	Inspected	
Chilled Water System	Does not Exist	
Condenser Water Distribution: Piping, Pumps and Auxiliaries	Does not Exist	
Cooling Coil in Ductwork	Does not Exist	
Cooling Tower	Does not Exist	
DX Split System	Inspected	
Indoor Unit	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Outdoor Unit	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Dry Cooler	Does not Exist	
Packaged / Rooftop Unit	Does not Exist	
Packaged Terminal A/C	Does not Exist	
Refrigerant Leak Detection System	Does not Exist	
Refrigerant Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Return Fan	Does not Exist	
CENTRAL ACID WASTE NEUTRALIZING TANK	Does not Exist	
CLIMATE CONTROL SYSTEM	Does not Exist	
COMPACTOR	Does not Exist	
CONVEYING	Does not Exist	
DOMESTIC WATER SYSTEM	Inspected	
DOMESTIC WATER SYSTEM  Domestic Cold Water System	Inspected	
Domestic Cold Water System	Inspected	

#### **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
DOMESTIC WATER SYSTEM	-	
Domestic Cold Water System		
Water Service		
Instance	MER-8	
Instance Condition	3 - Fair	
Instance Quantity	1	
Instance Quantity Uom	EACH	
Deficiency	No deficiencies recorded	
Domestic Hot Water System	Inspected	
Domestic Hot Water Remote Storage Tank	Does not Exist	
Domestic Water Heat Exchanger	Does not Exist	
Electric Domestic Water Heater	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Gas Fired Domestic Water Heater	Does not Exist	
Heat Pump Domestic Water Heater	Does not Exist	
Oil Fired Domestic Water Heater	Does not Exist	
Domestic Water Distribution Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
DRAIN/WASTE/VENT AND STORM SYSTEM	Inspected	
Interior Storm Piping	Does not Exist	
Sewage/Waste/Vent Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Sewage Ejector Pump	Does not Exist	
Sump Pump	Does not Exist	
DUAL TEMPERATURE SYSTEM (CHILLED AND HOT WATER)	Does not Exist	
FIXTURES	Inspected	
Staff And Other	Inspected	
Janitor Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Urinal	Does not Exist	
Student	Inspected	
Drinking Fountain	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Lavatory/Sink	Inspected	
Condition	3 - Fair	
- · · · · · · · · · · · · · · · · · · ·		
Deficiency	No deficiencies recorded	

#### **Building Condition Assessment Survey 2023 - 2024**

uestion	Response	
FIXTURES		
Student		
Sink And Fountain Combo Unit	Does not Exist	
Toilet	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Urinal	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
GAS FIRED FURNACE	Does not Exist	
GAS SERVICE	Does not Exist	
HEATING	Inspected	
Heating Coil In Ductwork	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Hydronic Heating	Does not Exist	
Radiator/Convector/Fin Tube	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Steam Heating	Does not Exist	
Steam supplied by External Sources	Does not Exist	
Unit Heater/Cabinet Heater	Does not Exist	
HEATING PLANT	Does not Exist	
Enclosed IDF Room	Does not Exist	
KITCHEN	Does not Exist	
MDF Room	Does not Exist	
SCIENCE DEMO ROOM	Does not Exist	
SCIENCE LAB	Does not Exist	
SCIENCE PREP ROOM	Does not Exist	
SPRINKLERS, STANDPIPE, FIRE SYSTEM	Inspected	
Dry Sprinkler Alarm Valve Assembly	Does not Exist	
Wet Sprinkler Alarm Valve Assembly	Does not Exist	
Fire Booster Pump Assembly	Does not Exist	
Roof Tank	Does not Exist	
Siamese Connection	Does not Exist	
Sprinkler Head  Condition	Inspected 3 - Fair	
	No deficiencies recorded	
Deficiency Sprinkler Piping	Inspected	
Condition	3 - Fair	
Deficiency	No deficiencies recorded	
Standpipe System	Does not Exist	
Water Gong	Does not Exist	
SWIMMING POOL	Does not Exist	
VENTILATION VENTILATION	Inspected	
Is the building mechanically ventilated?	Yes	
Exhaust Fan	Inspected	
Panaust Fall	nispected	

#### **Building Condition Assessment Survey 2023 - 2024**

Mechanical Inspection Q822 Question Response VENTILATION **Exhaust Fan** Inspected Condition 3 - Fair Deficiency No deficiencies recorded **Heating And Ventilating Unit** Does not Exist **Metal Ductwork** Inspected Are there any uninsulated ductwork by design in Mechanical Rooms? No Are there chain operated dampers? No Condition 3 - Fair Deficiency DAMAGED/MISSING INSULATION Deficiency Location/Instance MER M-8 25 **Deficiency Quantity** Quantity Uom L.F. MAINTENANCE Potential Action Urgency of Action PRIORITY 3 Purpose of Action LEVEL 2 Deficiency Photo1 No photo recorded Violations No violations recorded. **Supply Fan** Does not Exist **Unit Ventilator** Does not Exist